



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: EMILY TAN		Ref: CS/FCI24120041/Aqh3m4(N) Date: 03/03/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 3963K	Veh. Inspected	SKL 9677U
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010388MFCT	Excess (\$)	0.00
Assign From	EILEEN WANG	Assign Date	03/12/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	BMW 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WBA3A16000NS36171	Colour	WHITE
Odometer	268981 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/45R17	MICHELIN	6 mm
L/H Front Tyre	245/45R17	MICHELIN	6 mm
R/H Rear Tyre	245/45R17	MICHELIN	6 mm
L/H Rear Tyre	245/45R17	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	25/11/2024	Inspection Date	02/12/2024
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	