

REF: CS | C3-000124120055 | Tnh3

Phd's

PLEASE ARRANGE TO SURVEY
VEHICLE AT PANDAN ROAD

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 04/12/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 26/11/2024

Vehicle No : GBH-9042-D

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR FENDER RH	RESTORE Rp	
1	TAILLAMP RH	290.00	over
1	TAILLAMP LOWER PANEL RH	124.50	ok
1	REAR BUMPER	RESTORE Rp	
Sub Total		414.50	
Discount 25% On Parts		(103.63)	
<u>Special Nett Item</u>			
1	ADVERTISMENT STICKER	300.00	net

Date : 04/12/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 26/11/2024

Vehicle No : GBH-9042-D

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	300.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	600.00	400
	TO RESPRAY AFFECTED AREAS	600.00	500
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	✓
	RUST PROOFING	50.00	30
	Sub Total	1280.00	
	Remarks:		
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company	1,890.88	
	acknowledged by Repairer		
	re:		
	SUB TOTAL		
	GST 9.0 %	170.18	
	TOTAL	2,061.05	

Surveyor's name:

Tanfer 9749544

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

WP 4/12/24 430pm 04 days

p/p Resurvey new parts.