

Huey Yon (LKKAUTO)

From: Huey Yon (LKKAUTO)
Sent: Wednesday, 22 January 2025 11:52 AM
To: Taufikh (LKKAUTO); toh.jing.xuan@sime.com
Cc: raymond.yeo@sime.com; pml-pbsp@sime.com
Subject: RE: URGENT / FINAL REPORT / SLT1161P
Attachments: SLT 1161P-Mark estimate.pdf

Dear Sir/Mdm,

Without prejudice

We will be advising our principal a cost of repair of \$2,497.70 with 3 days of repair, subject to their approval.

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Sent: Monday, 20 January 2025 5:22 PM
To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: FW: URGENT / FINAL REPORT / SLT1161P

From: Toh Jing Xuan <toh.jing.xuan@sime.com>
Sent: Monday, 20 January 2025 5:21:23 pm (UTC+08:00) Kuala Lumpur, Singapore
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Finalization <finalization@lkkauto.com>
Cc: Teng Wai Khan <teng.wai.khan@sime.com>; Keith Leo Chi Yung <keith.leo.chiyung@sime.com>; Wai Ming Hui <wai.ming.hui@sime.com>; Raymond Yeo <raymond.yeo@sime.com>; PBSP <pml-pbsp@sime.com>
Subject: RE: URGENT / FINAL REPORT / SLT1161P

Dear Taufikh,

Please assist to confirm the COR for SLT1161P.

Thank you.

Toh Jing Xuan (Ms)
Aftersales, Bodyshop
toh.jing.xuan@sime.com



Performance Motors Limited (197401559W)
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
T: 1800-2255-269 **W:** www.pml-bmw.com.sg

From: PBSP <pml-pbsp@sime.com>

Sent: Thursday, December 26, 2024 4:45 PM

To: Taufikh (LKKAUTO) <taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Finalization <finalization@lkkauto.com>

Cc: Teng Wai Khan <teng.wai.khan@sime.com>; Keith Leo Chi Yung <keith.leo.chiyung@sime.com>; Toh Jing Xuan <toh.jing.xuan@sime.com>; Wai Ming Hui <wai.ming.hui@sime.com>; Raymond Yeo <raymond.yeo@sime.com>

Subject: URGENT / FINAL REPORT / SLT1161P

Dear Sirs

We refer to the above and attached Final Report.

Please assist to confirm COR as follows:

Total Labour : 2,282.00

Total Parts : 215.70

Total Labour & Parts (before GST) : 2,497.70

***MCA requested for 3 repair work days

Thank you.

Regards

Winnie / HM / CT

Aftersales, Bodyshop

BMW

Performance Motors Ltd

DDI: +65 6319 0175

FAX: +65 6479 4601

Address: 303 Alexandra Road, Singapore 159941

Email: pml-pbsp@sime.com

www.bmw.com.sg



Performance Motors Limited (197401559W)

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

T: 1800 2255 269 W: www.pml-bmw.com.sg

