

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: China Taiping Insurance (S) Pte Ltd

Policy No: _____ Third Party

Date: _____ 04.12.2024

Accident Date : 18.10.2024

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
1pc	<p>Estimate Cost of Repair to "Hino" Reg. No. YP8952U Claiming Against Your Insured Veh. No. PC8628G</p> <hr/> <p>Taillamp RH <i>cm</i></p> <p>Less 10%</p> <p>Labour Charge - Panel Beating, Repairing Of Rear Woden Side Gate Latch, Metal Frame & Part Replacement</p> <p>To Respray Affected Areas</p>		<p><i>295.00</i></p> <hr/> <p>-</p> <hr/> <p>-</p> <hr/> <p>300.00 <i>1001</i></p> <hr/> <p>300.00 <i>1501</i></p> <hr/> <p>Total : 600.00</p>

*NOT Withheld
Penny After Pain
1 day
@ 515.50*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: