

CARSMITH PRIVATE LIMITED

PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875

Tel: 9091 0000/ Email: claims@carsmith.biz

VEHICLE NO: GBM7443S

MAKE & MODEL: TOYOTA HIACE

DOA: 02.12.2024

CLAIM TYPE: TP CLAIM

Not Authorized
near
5/12/24

4 days
1/5 @ 2400
take photo. After repair

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 2,598.00	R X
TAILGATE RUBBER TOP GARNISH	1	\$ 254.00	11 X
TAILGATE RUBBER	1	\$ 328.50	11 X
TAILGATE LOCK	1	\$ 285.10	11 X
TAILGATE HINGE	2	\$ 190.50	11 X
TAILGATE ABSORBER	2	\$ 590.00	11 X
TAILGATE CENTER GARNISH	1	\$ 186.50	11 X
TAILGATE HANDLE	1	\$ 255.00	11 X
TAILGATE INNER BOARD	1	\$ 335.20	11 X
TAILGATE LOCK ACTUATOR	1	\$ 430.60	11 X
TAILGATE EMBLEM LOGO	1	\$ 108.00	new 98.10
TAILGATE WINDSCREEN MOULDING	1	\$ 218.50	NS X
TAILGATE WINDSCREEN	1	\$ 1,250.00	11 X
TAILGATE STOPPER	2	\$ 80.00	11 X
REAR END PANEL INNER	1	\$ 912.70	R X
REAR END PANEL OUTER	1	\$ 486.50	DO
REAR FLOOR BOARD PANEL	1	\$ 2,381.40	11 X
INNER BUMPER PLATE	1	\$ 325.00	NFX
REAR LAMP left panel LH	1	\$ 640.00	11 X
REAR LAMP right panel RH	1	\$ 640.00	DO/3rd
REAR BUMPER	1	\$ 698.00	2e/10m
REAR BUMPER SIDE RETAINER	2	\$ 161.60	11 X
REAR BUMPER LOWER SUPPORT BRACKET	4	\$ 244.80	5ULX

\$ 13,599.90

LESS 25%

\$ 3,399.98

SUB TOTAL

\$ 10,199.93

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	new 3.2 S/N
REAR NUMBER PLATE	1 SET	\$ 80.00	11 X
TAILGATE STICKER '70KM/H' 8'8 pax'	1	\$ 45.00	new 2.0 S/N
TAILGATE STICKER 'HIACE'	1	\$ 45.00	new S/N
REVERSE SENSOR	1 SET	\$ 480.00	modification 2.0 S/N
REVERSE CAMERA	1 SET	\$ 480.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X

SUB TOTAL \$ 1,300.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	11 X

PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	600
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,600.00	600
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	30
SUB TOTAL		<u>\$ 4,020.00</u>	

GRAND TOTAL \$ 15,519.93

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1922-6
252
P-1441-95
S.W 295
L-11280
3016-95
202
2413