

F.T.FASTTRACK

25 KAKI BUKIT ROAD 4 #01-77 SYNERGY @ KB SINGAPORE 417800

TEL: 6749 1002 FAX NO : 6385 2138

RCB REG NO: 50233100C

Email : freddietan2010@gmail.com

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL : 6389 6111 FAX : 6222 1033

ATTN : CLAIM DEPT

DATE : 25/11/2024

REF NO : SF0C24BCM001

VEH NO.: FBP3789E

YAMAHA YZF-R15V3

not Allowed
mess
5/12/24
2/5 \$3700
highlyptery...
4 days

RE: ESTIMATION FOR ACCIDENT INVOLVING VEH NO.FBP3789E /SLG5644E ON 10/11/2024

ITEM	QTY	DESCRIPTION	PRICE(S\$)
1	1	HANDLE BAR (LH)	Sub 175.00
2	1	BALANCER SET	Cu 60.00
3	1	CLUTCH LEVER	Cu 68.00
4	1	CLUTCH CABLE	Tor 55.00
5	1	MIRROR (LH)	Cu 110.00
6	1	HEADLAMP PANEL \$135	Cu 967.50
7	1	COVER FRONT	Cu 115.00
8	1	COVER OUTER (LH)	Cu 175.00
9	1	COVER INNER (LH)	Cu 115.00
10	1	FRONT SIGNAL LAMP (LH)	Cu 75.00
11	1	COVER LOWER (LH)	Cu 105.00
12	1	TANK COVER CENTER	Cu 155.00
13	1	METER PANEL	11 105.00
14	1	SIDE STAND	Sub 115.00
15	1	BODY SLIDER SET	Cu 160.00
16	1	SWIM ARM	Cu 780.00
17	2	FRONT& REAR FOOTREST (LH)@\$52.00	Cu 104.00
18	2	FRONT & REAR FOOTREST HOLDER @\$135	Cu 270.00
19	1	EXHAUST CAP	Cu 72.00
20	1	REAR FENDER	Cu 145.00
21	1	REAR WHEEL RIM	Cu 540.00
22	1	REAR WHEEL SHAFT	17 90.00
23	1	GEAR PEDAL	Sub 190.00
24	1	UNDER COVER REAR CENTER	17 125.00
25	1	TAIL LIGHT	Sub 220.00
26	2	TAIL COVER (LH)&(RH)@\$175.00	Cu 350.00
27	1	REAR BRACKET COVER	Cu 90.00
28	1	HOLDER BRACKET	Sub 110.00
29	1	DIFECTOR	Mis 38.00
30	2	REAR SIGNAL LAMP (LH)&(RH)@\$75.00	Cu 150.00
31	1	REAR SIGNAL HOLDER inner	Cu 75.00
32	1	REAR NO. PLATE	Cu 30.00
33	1	NO. PLATE LIGHT	Sub 55.00

TOTAL PARTS 5,989.50
LESS 10% 598.95
TOTAL 5,390.55

LABOUR & MISC
TOWING FEE 90.00
LABOUR CHARGE 400.00
GRAND TOTAL : 5,880.55



AUTHORISED SIGNATURE

KK Auto Consultants hence notify

the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts for rectification

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4832