



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: MOHD SHARIN			Ref: CS/LIP24120073/Unh3m4(N) Date: 08/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFS 955Z	Veh. Inspected	YN 9973M	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS24/3750	Excess (\$)	0.00	
Assign From	MOHD SHARIN	Assign Date	05/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER FEB21ER3SDEB		c.c	2998
Engine No.	HIDDEN		Year of Reg.	
Chassis No.	FEB21EA10503		Colour	RED / WHITE
Odometer	353928 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	AUSTONE	6 mm	
L/H Front Tyre	195 R15	AUSTONE	6 mm	
R/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm	
L/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2024		Inspection Date	05/12/2024
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)REGISTRATION DATE: 28 OCT 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	