

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

NTUC INCOME INSURANCE CO-OP LTD

1 MARITIME SQUARE

#10-01 HARBOURFONT CENTRE

SINGAPORE 099253

YR922Z

ESTIMATE

VEHICLE NO : SMT9474Y
MAKE/MODEL : TOYOTA SIENTA
ACC DATE : 28/11/2024

Not Authorized
for
merch
5/12/24
1/5 \$ 15,400
the photo after rep-
4 days

PARTICULAR		UNIT PRICE		AMOUNT	
QTY		SS		SS	
	<u>LIST PRICE</u>				
1	1 FRONT DOOR -LH	1650	1890.60	Body RD	1,890.60 ✓
2	1 FRONT DOOR SIDE MIRROR		1210.35	BRD	1,210.35 ✓
3	1 FRONT DOOR SIDE MIRROR COVER		181.43	BRD	181.43 ✓
4	1 FRONT DOOR OUTER HANDLE		190.65	17	190.65 X
5	1 FRONT DOOR GLASS		991.50	Shotland	991.50 ✓
6	1 FRONT DOOR GLASS OUTER MOULDING		191.63	Bent	191.63 ✓
7	1 FRONT DOOR GLASS INNER MOULDING		181.50	Bent	181.50 ✓
8	1 FRONT DOOR GLASS RUN CHANNEL		248.50	17	248.50 X
9	1 FRONT DOOR GLASS GUIDE		110.50	17	110.50 X
10	1 FRONT DOOR GLASS REGULATOR		481.90	Bent	481.90 ✓
11	1 FRONT DOOR GLASS REGULATOR MOTOR		360.90	IM	360.90 ✓
12	1 FRONT DOOR 1/4 GLASS		280.63	Shotland	280.63 ✓
13	1 FRONT DOOR 1/4 GLASS RUBBER		89.92	CUT	89.92 ✓
14	1 FRONT DOOR INNER LOCK		661.59	Daye/IM	661.59 ✓
15	1 FRONT DOOR INSULATION		130.20	RE	130.20 ✓
16	1 FRONT DOOR INNER TRIM BOARD		891.66	2x17m	891.66 ✓
17	1 FRONT DOOR W/STRIP		260.92	Trim	260.92 ✓
18	1 FRONT DOOR OPENING W/STRIP		311.43	17	311.43 X
19	1 FRONT DOOR CHECKER		120.65	Trim	120.65 ✓
20	2 FRONT DOOR HINGES		131.50	Bent	263.00 ✓
21	1 FRONT DOOR PILLAR		665.90	2x17m	665.90 ✓
22	1 FRONT DOOR PILLAR INNER TRIM		291.93	17	291.93 X
23	1 FRONT DOOR PILLAR OUTER GARNISH		286.95	17	286.95 X
24	1 FRONT DOOR WIRE HARNESS		488.63	R	488.63 X
25	1 FRONT FENDER -LH		891.66	Body RD	891.66 ✓
26	1 FRONT FENDER INNER SHIELD		154.43	Trim	154.43 ✓
27	1 FRONT FENDER ENCLOSURE		141.42	Trim	141.42 ✓
28	1 FRONT SHOCK ABSORBER -LH		481.90	Bent	481.90 ✓
29	1 FRONT LOWER ARM		760.60	Bent	760.60 ✓
30	1 FRONT KNUCKLE ARM		581.60	Bent	581.60 ✓
31	1 FRONT WHEEL HUB		280.90	Bent	280.90 ✓
32	1 FRONT WHEEL BEARING		241.60	RE	241.60 ✓
33	1 FRONT ANTI ROLL BAR		481.90	17	481.90 X
34	1 FRONT ANTI ROLL BAR LINK		180.90	17	180.90 X
35	1 FRONT DRIVE SHAFT -LH		1310.90	IM	1,310.90 X
36	1 FRONT STEERING RACK ASSY		1785.90	Bent/Trim	1,785.90 ✓
			BALANCE B/F		18,076.58

T K LEE AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
		BALANCE C/F	18,076.58
37	1 FRONT STEERING RACK CROSSMEMBER	2055.60 <i>DD/sat</i>	2,055.60 ✓
38	1 SLIDING DOOR -LH	1999.50 <i>DD/sat</i>	1,999.50 ✓
39	1 SLIDING DOOR OUTER HANDLE	190.65 <i>cut</i>	190.65 ✓
40	1 SLIDING DOOR GLASS OUTER MOULDING	181.66 <i>11</i>	181.66 X
41	1 SLIDING DOOR GLASS RUN CHANNEL	281.43 <i>11</i>	281.43 X
42	1 SLIDING DOOR GLASS REGULATOR	481.90 <i>11</i>	481.90 X
43	1 SLIDING DOOR INSULATION	130.20 <i>11</i>	130.20 X
44	1 SLIDING DOOR SEAMING SEAL	811.43 <i>11</i>	811.43 X
45	1 FRONT WINDSCREEN	1881.42 <i>cro nic</i>	1,881.42 X
46	1 (SET) FRONT WINDSCREEN MOULDING	141.83 <i>11</i>	141.83 X
47	1 DASHBOARD	1723.80 <i>cut/trim</i>	1,723.80 ✓
48	1 DASHBOARD EXTENSION	1699.42 <i>trim</i>	1,699.42 ✓
49	1 DASHBOARD SIDE COVER -LH	186.43 <i>11</i>	186.43 X
50	1 GLOVE BOX	411.59 <i>11</i>	411.59 X
51	1 SLIDING DOOR PROTECTOR	260.90 <i>11</i>	260.90 X
			30,514.34
		LESS 25%	7,628.59
			<u>22,885.76</u>

T K LEE AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
SPECIAL NETT ITEMS			
1	1 FRONT WHEEL RIM -LH	180.00	180.00
2	1 (SET) FRONT WHEEL RIM CAP	180.00	180.00
3	1 FRONT TYRE	160.00	160.00
4	1 (SET) FRONT FENDER INNER SHIELD CLIP	60.00	60.00
5	1 (SET) FRONT DOOR BLACK TAPE	120.00	120.00
6	1 FRONT DOOR GLASS SOLAR FLIM	180.00	180.00
7	1 (SET) F/R DOOR VISOR	350.00	350.00
8	1 (SET) FRONT WINDSCREEN SEALANT	80.00	80.00
			1,310.00

LABOUR CHARGES :			
1	TO REMOVE AND REFIX FRONT WINDSCREEN	180.00	180.00
2	TO REMOVE & REPLACE FRONT UNDERCARRIAGE PARTS	550.00	550.00
3	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	120.00	120.00
4	TO REMOVE & REPLACE DASHBOARD	380.00	380.00
5	TO REMOVE & REFIX FRONT SEAT, INTERIOR TRIMS TO ASSIST REPAIR	150.00	150.00
6	TO REMOVE & REFIX AIRCON COOLING SYSTEM AND REFILL AIRCON GAS	180.00	180.00
	TO VACUUM, WAXING AND CLEANING INTERIOR	180.00	180.00
7	TO CHECK FRONT WIRING	120.00	120.00
8	TO TUFF KOTE	120.00	120.00
9	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,400.00	1,400.00
10	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	1,500.00	1,500.00
TOTAL:			4,880.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 29,075.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey

Resurvey shall be on a "Without Prejudice" basis

Modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

7-2/602.66
25-6
16202.00
450
2660
19312
202
15-449