

EURO SUCCESS SERV PTE.LTD

1 Kaki Bukit Ave 6,#02-03 Singapore 417883

Tel : 67426231 Fax : 67411019 H/P : 98289277 (AH HUAT)

not Authorized
dik
mar 15
5/2/25
d/s 11,000
Telephone Atty.
6 days

VEHICLE No : PD 1240G

1PC	FRONT PANEL	3619.80	Body	\$8,500.00
1PC	FRONT WIPER ARM		an	\$450.00 X
1PC	FRONT GRILLE OUTER	1866.10	one	\$2,110.00
1PC	FRONT GRILLE INNER	1450.20	one	\$1,850.00
1PC	FRONT GRILLE LOGO		one	\$150.00
1PC	FRONT RADAR SENSOR COVER	280.00	one	\$450.00
1PC	FRONT RADAR SENSOR UNIT		See	\$4,500.00 X
1PC	HEADLAMP N/S	2495.90	one	\$2,680.00
1PC	HEADLAMP O/S		an	\$2,680.00 X
1PC	FRONT BUMPER		R	\$1,815.00 X
1PC	AIR CON BLOWER UNIT	1850.00	one	\$4,855.00
1PC	AIR CON HEATER UNIT	3599.20	one	\$5,209.00
1PC	FRONT CROSS MEMBER CENTRE		an	\$2,800.00 X
				\$38,049.00
				LESS 25% \$28,536.75

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$200.00 150
TO DISMANTLE & REFIX FRONT DASHBOARD	\$480.00 300
TO REFILL AIR CON GAS	\$100.00 ✓
TO SPRAY RUST PROOFING	\$100.00 30
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$500.00 200
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00 800
TO PUTTY & SPRAY PAINTING	\$1,500.00 680
TOTAL	\$32,666.75

P. 15311-2
252
11483.40
2280
13763.40
2076
11010

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: