

# SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Authorised  
du  
may  
9/12/24

4500

4 days

VEHICLE NUMBER: SMR7448Y  
MAKE & MODEL: NISSAN NOTE

nett item

TAILGATE	30A600	1352.80	\$1,861.90	✓
TAILGATE LOGO	neu		\$68.60	✓
TAILGATE "NOTE" EMBLEM	neu		\$79.90	✓
TAILGATE HINGES L/R X2	11		\$181.60	X
TAILGATE NUMBER PLATE LAMP L/R X2	11		\$188.80	X
TAILGATE GARNISH	but/cra		\$287.60	✓
TAILGATE SHOCK ABSORBER L/R X2	11		\$467.80	X
TAILGATE OUTER HANDLE	11		\$312.10	X
TAILGATE INNER LOCK	Daye/Jan	166.60	\$283.60	✓
TAILGATE STRIKER	11		\$56.20	X
TAILGATE WEATHERSTRIP	1w1	106.30	\$182.60	✓
TAILGATE WINDSCREEN MOULDING	neu		\$82.60	✓
TAILGATE INNER TRIMBOARD	11		\$311.20	X
TAILGATE INNER PULL POCKET	11		\$86.90	X
TAIL LAMP L/R X2	MSA1015 cra	347.90	\$1,186.40	126
REAR BUMPER	de	579.90	\$867.00	✓
REAR BUMPER SIDE RETAINER L/R X2	11		\$166.40	X
REAR BUMPER SIDE BRACKET L/R X2	11		\$210.00	X
REAR BUMPER REFLECTORS X2	11		\$179.20	X
REAR BUMPER SPONGE	11		\$162.60	X
REAR ANTENNA	cra	100.60	\$181.20	✓
END PANEL	10	597.20	\$712.10	✓
END PANEL GARNISH	1w1		\$142.30	✓
			\$8,258.60	
		Less 10%	\$825.86	
			<b>\$7,432.74</b>	

1 set	REAR REVERSE SENSOR	malfunction	\$280.00	200 S/W
	REAR REVERSE CAMERA	11	\$300.00	X
	REAR BUMPER CLIPS	neu	\$60.00	30 S/W
	TAILGATE TRIMBOARD CLIPS	11	\$50.00	X
	TAILGATE GARNISH CLIPS	11	\$30.00	X
	END PANEL GARNISH CLIPS	11	\$60.00	X
	END PANEL SEALANT	neu	\$100.00	50 S/W
	REAR NUMBER PLATE WITH GARNISH	11	\$70.00	X
	REAR WINDSCREEN SEALANT	neu	\$100.00	40 S/W
	REAR WINDSCREEN SPONGE	neu	\$60.00	20 S/W
			<b>\$1,110.00</b>	

TO CHECK REAR WIRING

\$50.00 20

TO REPLACE REAR REVERSE SENSOR

\$80.00 30

TO REMOVE AND REFIT REAR REVERSE CAMERA  
 TO REMOVE AND TRANSFER TAILGATE FITTINGS TO NEW  
 TO REMOVE, REFIT AND REPLACE REAR INTERIOR TRIM  
 TO REMOVE & REFIT REAR WINDSCREEN TO NEW TAILGATE  
 TO PROVIDE LABOUR, WORKMANSHIP  
 TO SPRAY PAINT ON AFFECTED PANELS  
 RUST PROOFING

11 \$100.00 X  
 \$100.00 50  
 \$120.00 60  
 \$180.00 120  
 \$1,000.00 600  
 \$1,000.00 850  
 \$180.00 50  
**\$2,810.00**

Total

**\$11,352.74**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3912-70  
 10%  
 3521.43  
 340  
 178  
 5641.43  
 218  
 4423