

(08/11/13) wef

ASS. REC.-BY: Marcus

REF:

CS/1424/20112/Unh3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBL5873Cat Workshop m/s MM

of _____

Insured: SMR3621P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: \$88kIDAC Accident Rpt: _____ Consistent?: **Yes** or **No**GIA / PR Seen: _____ Consistent?: **Yes** or **No**Est. Repairs: 3 days Res.: **Yes** or **No**Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

3 3000Vehicle: **IN** / **OUT**

Date: _____ Person Contacted: _____

Veh No: GBL5873C Yr Regn: 12/11/14Type: **M.Car** / **M.Cycle** / **Bus** / **Van** / **Lorry** / **Taxi** / **Prime Mover** /Truck / Trailer or CAMake: Toyota Dyna c.c. 2982Colour: white A/C: **Insured** / **Std** / **NI** / **NA**Sp. Reading: 123/137 T/Radio: **Insured** / **Std** / **NI** / **NA**

Eng/No: _____

C/No: KDY2318047707Gen. Cond: **Good** / **Fair** / **Poor** / **Burnt**Steering: **Inorder** / **Jammed** / **Leaked** / **Burnt** orBrake: **Inorder** / **Jammed** / **Leaked** / **Burnt** orModi: **Nil** / **S/Rim** / **STD A/Rim** orTyre Size: **F**: 195-12.5 MIC**R**: 235/50 R14**BS** / **DUN** / **EXNOVA** / **GY** / **FS** / **LIZA** / **MIC** / **OHTSU** / **PIR** / **SUMI** /**TOYO** / **YOKO** or Def. um

Front

Rear

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. 06/12/24 D.O.I. 20/03/25

Survey held at _____

Des. of Damages: **Frnt** / **Rear** / **O/S** / **N/S** / **U/C** / **Rooftop** orRear N/SThe **U/C** / **Chassis frame** / **Body Structure** affected due to collision.

Date / Time

Action / Instruction Dep 13k25/3/25 1/5 \$1100 in hand David

(red, \$ 3323.8, 75%)

Date/Time, File Pass to?

☐ : **Preli. Report**

Days Of Repair: _____

1)

☐ : **Final Report**

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : **Site Insp** (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : **Interview** (\$ _____)

Photos

☐ : **Tech. Invs** (\$ _____)

Others

☐ : **Weekend** (\$ _____)

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____)



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Not Authorized
do
now
20/3/25
1/5 & 1100/
the shopkeeper
3 days

Carplate: GBL5873C
Chassis No: KDY231-8047707
Accident Date: 06/12/2024
Make & Model: Toyota Dyna

No.	Item	Price	✓/✗	Remarks
1	Rear Tail Lamp LH	\$ 465.30	322-30	Che ✓
2	Rear Tail Lamp Panel LH	\$ 125.20		Shf ✓
3	Rear Tail Lamp Reflector LH	\$ 79.20		11 X
4	Rear End Panel	\$ 606.10		R X
5				
6				
7				
8				
Special Nett Items		Price	✓/✗	Remarks
1	Rear Reverse Sensor (1 Set)	\$ 280.00		11 X
2	Rear Box Door Pillar LH	\$ 980.00		PP/Buf 500 SW
3	Speed Sticker "70km/hr"	\$ 18.00		11 X
4				
5				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		11 X
2	Rewiring to Facilitate Repairs	\$ 150.00		20
3				
4				
5				
6	Labour to remove and replace Stainless Steel Floor panel. Side Panel, Door Pillars, Doors and All Necessary and Affected Areas Caused by Accident.	\$ 800.00		320
7	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 800.00		200
	Estimated No. of days for repairs and respray of all necessary	8 days		

4428.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-447.50
252
335.63
500
540
1375.63
212
1100

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	300C
Vehicle Details	
Vehicle No.:	GBL5873C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Mar 2025
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	1KDB079068
Chassis No.:	KDY2318047707
Maximum Power Output:	-
Open Market Value:	\$33,941.00
Original Registration Date:	12 Nov 2021
First Registration Date:	12 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$1,698.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,589.00
COE Rebate Amount:	\$28,305.00
Total Rebate Amount:	\$28,305.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 19 Mar 2025

OK

**\$79,800**

Instl. \$1,237 /mth

~\$13,570 /yr

📅 04-Feb-2021

(5yrs 10mths COE left)

🔧 53,327 km

2,982 cc

👤 1 Owner

Fuel Type: Diesel

New paint.

Posted 14-Mar-2025

Toyota Dyna 150 2.8M♥

\$84,800

Instl. \$1,187 /mth

~\$12,860 /yr

📅 22-Oct-2021

(6yrs 7mths COE left)

🔧 N.A

2,755 cc

👤 1 Owner

Fuel Type: Diesel

Y plate! 1 owner unit, superb condition! Brand new paintwork! Loan and insurance available. Call us now to view.

I-Deal Auto Trading Pte Ltd|Posted 12-Mar-2025

☐ Compare

★ StarAd View All

Toyota Hiace 2.0 DX Auto. Genuine Low Mileage.

Genuine Low Super Low Mileage Unit. Low Maintenance. One Owner. Direct Owner

[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]

PRIME MOTOR
& LEASINGWith over 200 units of vehicles to choose from,
ranging from all European to Japanese Makes.

Think One Automobile



NEW & USED COMMERCIAL VEHICLES



Toyota Dyna 150 2.8M♥

\$84,800

Instl. \$1,187 /mth

~\$12,860 /yr

📅 22-Oct-2021

(6yrs 7mths COE left)

🔧 N.A

2,755 cc

👤 1 Owner

Fuel Type: Diesel

Y Plate! 1 Owner unit! In superb condition Brand new paintwork. Loan and Insurance available. Call us now to view.

I-Deal Auto Trading Pte Ltd|Posted 12-Mar-2025

☐ Compare

PREMIUM AD

Toyota Dyna 150 2.8M♥

\$84,800

Instl. \$1,200 /mth

~\$12,980 /yr

📅 29-Sep-2021

(6yrs 6mths COE left)

🔧 81,000 km

2,755 cc

👤 2 Owners

Fuel Type: Diesel

Y-plate. 10ft truck with cabin height box, no repair needed, high loan applicable and trade in acceptable. Call our sales team now for viewing and test driving.

Think One Automobile & Trading|Posted 10-Mar-2025

☐ Compare

Toyota Dyna 150 3.0M♥

\$83,800

Compare