

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

CHINA TAIPIING

06 DEC 2024

Page No. : 1 of 5

Estimate No. : b1 72040
Date Estimated : 06/12/2024
Prepared By : Tee Hong Da

- ESTIMATE REPAIR FOR -

Thangam D/O Krishnan
1E Green Lane

Singapore 438891

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX3366R	WBA12AK0007H40981	23/03/2021	2191 Gran Coupe	39537

DESCRIPTION**VALUE**

To replace front bumper, make good front right fender, front right driver door and attachment

1700 3,400.00

To respray front bumper, front right fender, front right door, front right door handle, and attachment

1923 2,882.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

✓ 531.00

To check electrical wiring system at the front section for proper function.

✓ 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

✓ 177.00

Sundries. nec

80 ? 150.00

Total Labour 1: 7,317.00

DESCRIPTION**QTY****PRIC****VALUE**

ALLOY RIM 7.5JX17 DOUBLE SPK 548

1

998.60

cut ✓ 998.60

IMPACT ABSORBER TOP

1

89.60

nn x 89.60

RH FOG LAMP SUPPORT

1

144.55

nn x 144.55

FRT BUMPER BOTTOM CARRIER

1

177.80

nn x 177.80

RH FOG LAMP COVER

1

50.75

xnn cut x 50.75

FRT BUMPER PANEL PRIMED (PDC/PMA)

1

987.80

de ✓ 987.80

SET MOUNTING PDC/PMA SENSOR FRT

1

75.55

xnn x 75.55

DECOUPLING RING

1

5.65

xnn x 5.65

Ultrasonic s

1

391.05

nn x 391.05

Total Parts : 2,921.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 72040
Date Estimated : 06/12/2024
Prepared By : Tee Hong Da

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX3366R	WBA12AK0007H40981	23/03/2021	218i Gran Coupe	39537

Tanjin 97495749/62563561
- wp' 08/01/24 @ 1030pm
p/f Resurvey before paint
tanjin ekkhanto.com.
6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	7,317.00
Parts	:	2,921.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	921.45
Grand Total	:	11,159.80

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT NOTICE