

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0916/2024/EQ
DATE : 10-Dec-24
WIP : 41302

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Steve,

12 Days + 2 Sun + 1 PH - OK - Allan Boo

19-Feb-25

OWNER'S NAME : MR LOW CHIN CHYE
ADDRESS : 30 MARGATE ROAD
SINGAPORE 438070

TELEPHONE : HP +65 97528284
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070148447-04
VEHICLE NO : **SDM 8800 P**
MODEL CODE : AUDI A3 SPORTBACK 1.4 TFS
MODEL YEAR : 23/10/2020
ENGINE NO : CZE 866150
CHASSIS NO : WAUZZZ8V4LA084000
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Dec-24
PLACE OF ACCIDENT : 8C TANJONG RHU ROAD, SINGAPORE 436891
CARPARK LOT 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8800 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	\$ 1,600.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	\$ 1,600.00
4	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	\$ 3,000.00
5	TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR END PANELLING, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL AND DOOR ENTRANCE.	\$	4,600.00	\$ 2,475.00
6	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	500.00	\$ 500.00
SUBTOTAL LABOUR CHARGES		: \$	13,480.00	\$ 9,455.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8800 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
				\$ 9,455.00
7	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	S/N \$	400.00	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		:	\$ 14,172.00	\$ 9,747.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8800 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,483.00	\$	1,986.40
2	REAR BUMPER FIXING PARTS	1	\$ 216.00		
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 36.00		
4	REAR WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 96.00		
5	REAR BUMPER SPOILER	1	\$ 297.00		
6	REAR BUMPER REFLECTOR - LH	1	\$ 41.00		
7	REAR BUMPER GUIDE SECTION - LH	1	\$ 84.00	\$	66.96
8	REAR SIDE PANEL - LH	1	\$ 5,131.00	\$	4,104.80
9	REAR WHEEL HOUSING LINER - LH	1	\$ 289.00		
10	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 67.00		
11	REAR OUTER TAIL LIGHT - LH	1	\$ 1,656.00	\$	1,324.80
12	REAR QUARTER GLASS - LH	1	\$ 365.00	\$	291.60
13	REAR QUARTER GLASS CHROME TRIM STRIPS - LH	1	\$ 326.00	\$	260.40
14	REAR ROOF CHROME MOLDING - LH	1	\$ 741.00		
15	1/4 GLASS SEALANT	S/N	\$ 100.00	\$	100.00
16	METAL FILTER POWDER	S/N	\$ 280.00	\$	280.00
17	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
18	STONE CHIP	S/N	\$ 180.00	\$	180.00
19	CAVITY WAX	S/N	\$ 140.00	\$	140.00
	ADD PARTS - SUPPLEMENTARY			\$	106.80
20	SUNDRIES		\$ 800.00	\$	34.88
TOTAL SPARE PARTS		:	\$ 13,508.00	\$	9,056.64
TOTAL LABOUR CHARGES		:	\$ 14,172.00	\$	9,747.00
GRAND TOTAL		:	\$ 27,680.00	\$	18,803.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0916/2024/EQ 2-Jan-25 JOON HONG 1 of 1 SDM 8800 P AUDI A3 SPORTBACK 1.4 TFS
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	SOUND ABSORBER S/N	\$ 134.00	\$ 106.80
GRAND TOTAL		\$ 134.00	\$ 106.80

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT