



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--|---|------------|
| MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 ON BEHALF OF LUMENS PTE LTD | | | Ref: CS/TP24120129/Evh3e2(N) Date: 08/01/2025 Code: TP508 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | Veh. Inspected | SNK 9249S | |
| | Policy No. | Coverage (\$) | 0.00 | |
| | Claim No. | Excess (\$) | 0.00 | |
| | Assign From | Assign Date | 09/12/2024 | |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | NISSAN SERENA | c.c | 1198 |
| | Engine No. | HIDDEN | Year of Reg. | 2023 |
| | Chassis No. | JN1EBAC27Z0001792 | Colour | BLACK |
| | Odometer | 166190 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195/60 R16 | ATREZZO | 5 mm |
| | L/H Front Tyre | 195/60 R16 | ATREZZO | 5 mm |
| | R/H Rear Tyre | 195/60 R16 | ATREZZO | 5 mm |
| | L/H Rear Tyre | 195/60 R16 | ATREZZO | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 05/12/2024 | Inspection Date | 09/12/2024 |
| | Survey held at | MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 7 Working Days | |