

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliate data Fordenstian Intermedianala Dea Franceta For Automobile					
Affiliated to Federation Internationale Des Experts En Automobile					
MS	GREAT AMERICAN INSURANCE COMPANY		Ref:	CS3/GAI24120148/Enh3m4	
	3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER		Date:	17/12/2024	
	SINGAPORE 03919		Code:	GAI	
1.	Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SNH 3106B	Veh. Inspected	SMZ 1314Y	
	Policy No.	MOMVP000005732-00-000	Coverage	0	
	Claim No.	CLMOMVP000001623	Excess	\$0.00	
	Assign From	JOCELYN TENG	Assign Date	10/12/2024	
2.	2. Vehicle Details				
	Make & Model	TOYOTA C-HR	C.C	1797	
	Engine No.	2ZR8404807	Year of Reg.	26/02/2020	
	Chassis No.	ZYX102116334	Colour	GREEN	
	Odometer	206444 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60R17	GRENLANDER	6	
	L/H Front Tyre	215/60R17	GRENLANDER	6	
	R/H Rear Tyre	215/60R17	GRENLANDER	6	
	L/H Rear Tyre	215/60R17	GRENLANDER	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
5.		General Information			
	Accident Date	09/12/2024	Inspection Date	11/12/2024 (14:12)	
	Survey held at POSH AUTOWERKZ PTE LTD – 8 KAKI BUKIT AVE 4 #02-24, PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					

CTY

5b.

STEVE CHEN TSUE YEE

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Estimate Days of Repair