



Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

Attention To : **ECICS LIMITED**  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

### Claim Details

Case Ref. No. : OD/122024/7920  
Date : 09-12-2024  
Accident Date : 09-12-2024

### Vehicle Details

Make & Model : Honda JAZZ 1.3 CVT  
Chassis No : JHMGK3850LS216896  
Registration No : SMR8400C

*Not Lushonite  
Repair B4 repair  
Ex 8600h  
4 days*

| S/N               | Description                   | Qty   | Amount (\$)   |
|-------------------|-------------------------------|-------|---------------|
| 1                 | RH HEADLAMP                   | 1.00  | Wt \$410.00 ✓ |
| 2                 | RH HEADLAMP LOWER BRACKET     | 1.00  | Sn \$30.00 X  |
| 3                 | FRONT BUMPER                  | 1.00  | cm \$380.00 ✓ |
| 4                 | FRONT BUMPER RH SIDE RETAINER | 1.00  | Sn \$10.00 X  |
| 5                 | FRONT BUMPER CLIPS            | 10.00 | me \$20.00 ✓  |
| 6                 | FRONT RH FENDER               | 1.00  | R \$180.00 X  |
|                   |                               |       | \$1,030.00    |
| Margin: 10%       |                               |       | \$103.00      |
|                   |                               |       | \$1,133.00    |
| 7                 | TO RESET HEADLAMP SYSTEM      | 1.00  | \$280.00 2ol  |
| 8                 | TO REPAIR DAMAGES             | 1.00  | \$380.00 3ol  |
| 9                 | TO SPRAY PAINTING             | 1.00  | \$480.00 4ol  |
| Subtotal w/o GST: |                               |       | \$2,273.00    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged:

Signature:

Date: