

VOLKSWAGEN

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
ONG
CHUN WEI
BLK 431 CHUA CHU KANG AVE 4
#14-575

Document no.
Document date 10-12-2024
Customer no. 6151000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2024035447/ 1
Job order date 09-12-2024
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SDG1414Z	5G1RVR	24-02-2017	WWWZZZAUZH120792	Golf 2.0 R BM 206TSI D6A	149,732

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#8	280.00	305.20
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#8	480.00	523.20
5G0823031J	Hood	1	pcs.	2,030.18	#8	2,030.18	2,212.90
5G0807221BJGRU	Cover For Bumper Primed	1	pcs.	1,681.58	#8	1,681.58	1,832.92
5G0919493B	Sensor Bracket	1	pcs.	32.24	#8	32.24	35.14
5G0919493C	Sensor Bracket	2	pcs.	32.24	#8	64.48	70.28
5G0919494B	Sensor Bracket	1	pcs.	32.24	#8	32.24	35.14
5Q0919133 9B9	Seal Ring Satin Black	4	pcs.	1.63	#8	6.52	7.11
5G0807049A	Guide Piece	1	pcs.	50.43	#8	50.43	54.97
	BUMPER SIDE BRACKET LH						
5G0807050A	Guide Piece	1	pcs.	50.43	#8	50.43	54.97
	BUMPER SIDE BRACKET RH						
5G0805705H	Guide	1	pcs.	172.32	#8	172.32	187.83
	BUMPER CTR BRACKET						
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	94.98	#8	94.98	103.53
D 822150A1	Bonding Agent For Plastic	1	pcs.	78.24	#8	78.24	85.28
5G0807248F	Foam Insert	1	pcs.	100.10	#8	100.10	109.11
5G0853651E ADQ	Radiator Grille Satin Bla	1	pcs.	747.89	#8	747.89	815.20
	LABOUR	4	pcs.	840.00	#8	3,360.00	3,662.40
	SPRAY PAINT	4	pcs.	800.00	#8	3,200.00	3,488.00
	FRONT NUMBER PLATE	1	pcs.	80.00	#8	80.00	87.20
	INDIA DIRECT DOA: 7/12/2024 TP VEH NO: GBH6186S SURVEY BY:						

Quotation valid till 16-12-2024

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#8	760.00	11,781.63	9%	1,128.75	12,541.63	13,670.38
Total amount: 760.00 + 11,781.63 + 1,128.75 = 13,670.38						13,670.38

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer

Service Advisor