



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24120153/Kqh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	23/12/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5132A	Veh. Inspected	SNK 1976D
Policy No.	-	Coverage	0
Claim No.	AVS24/3846	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	10/12/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E 250CGI (A)	C.C	1796
Engine No.	27186030169867	Year of Reg.	01/04/2011
Chassis No.	WDD2120472A363046	Colour	METALLIC BLACK
Odometer	143255 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/45ZR17	GRENLANDER	8
L/H Front Tyre	235/45ZR17	GRENLANDER	8
R/H Rear Tyre	235/45ZR17	GRENLANDER	8
L/H Rear Tyre	235/45ZR17	GRENLANDER	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/12/2024	Inspection Date	11/12/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days