



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: ESTHER			Ref: CS/FCI24120155/Knh3m4(N) Date: 20/03/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1361L	Veh. Inspected	SBS 5062P
	Policy No.	D-24102356MFBP	Coverage (\$)	0.00
	Claim No.	D24010793MFBP	Excess (\$)	0.00
	Assign From	TEO SWEE KEONG	Assign Date	10/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	SCANIA KUB4X2 9.3L A/T ABS TURBO (A)	c.c	9290
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	YS2K4X20001867405	Colour	MULTI COLOUR
	Odometer	1158429 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70R22.5	BRIDGESTONE	9 mm
	L/H Front Tyre	275/70R22.5	BRIDGESTONE	9 mm
	R/H Rear Tyre	275/70R22.5 (D)	BRIDGESTONE	8/8 mm
	L/H Rear Tyre	275/70R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/12/2024	Inspection Date	11/12/2024
	Survey held at	15 ANG MO KIO ST 63 SINGAPORE 569117		
	Repairer	SBS TRANSIT LTD		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	