



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: SAM LOW			Ref: CS/LIP24120180/Tqh3m4(N) Date: 14/01/2025 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	SNG 6498E	Veh. Inspected	SKZ 8727S
	Policy No.	SI23V08789/VPC/RO1/E00	Coverage (\$)	0.00
	Claim No.	IVS24/1235	Excess (\$)	0.00
	Assign From	SAM LOW	Assign Date	12/12/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	PEUGEOT 3008	c.c	1560
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	VF30U9HD8FS196758	Colour	RED
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/50R17	MICHELIN	6 mm
	L/H Front Tyre	225/50R17	MICHELIN	6 mm
	R/H Rear Tyre	225/50R17	MICHELIN	6 mm
	L/H Rear Tyre	225/50R17	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/06/2024	Inspection Date	18/12/2024
	Survey held at	TRUST FELLAS AUTO SERVICE PTE LTD 40 TOH GUAN ROAD EAST, #01-65, ENTERPRISE HUB, SINGAPORE 608582		
<b>5a. Remarks</b>				
	A)REGISTRATION DATE: 05 FEB 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	