

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SLV9836M

Make & Model: Honda Shuttle Hybrid

Chassis number:GP71202307

No.	Description of spare parts	Qty	Amount S\$	
1	Bonnet x R	1	\$ 1,121.00	
2	Bonnet lock x nn	1	\$ 135.00	
3	Bonnet RH hinge x nn	1	\$ 81.00	
4	Bonnet LH hinge x nn	1	\$ 81.00	
5	Bonnet rubber seal x nn	1	\$ 126.00	
6	Front bumper / BR	1	\$ 1,051.00	/
7	Front bumper clips / Nec	1set	\$ 70.00	30 /
8	Front bumper RH side retainer / BR	1	\$ 22.00	/
9	Front bumper LH side retainer / BR	1	\$ 22.00	/
10	Front bumper tow cover / CRU	1	\$ 46.00	/
11	Front bumper lower grille / BR	1	\$ 146.00	/
12	Front bumper reinforcement / DD	1	\$ 332.00	/
13	Front bumper RH fog lamp cover x nn	1	\$ 78.00	
14	Front bumper LH fog lamp cover x nn	1	\$ 78.00	
15	Front grille outer chrome / BR	1	\$ 256.00	/
16	Front grille / BR	1	\$ 405.00	/
17	Front grille emblem / Nec	1	\$ 38.00	/
18	Front grille clips / Nec	1set	\$ 50.00	15 /
19	RH headlamp assy / BR	1	\$ 1,550.00	/
20	RH headlamp lower bracket / BR	1	\$ 45.00	/
21	LH headlamp assy / BR	1	\$ 1,550.00	/
22	LH headlamp lower bracket / BR	1	\$ 45.00	/
23	Support panel x nn	1	\$ 781.00	
24	Support panel upper cover x nn	1	\$ 96.00	
25	Support panel upper cover clips x nn	1set	\$ 60.00	
26	Aircon condenser x nn	1	\$ 903.00	

5,553

-20%

4,442.40

	\$	9,168.00
Part less 20%	\$	1,833.60
Total:	\$	7,334.40

No.	Special Nett Items	Qty	Amount S\$
1	Front number plate / BR	1	\$ 70.00
2	Radiator coolant x nn	1	\$ 70.00

50 /

50

Total: \$ 140.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 70.00
4	Apply rust coating chemical on affected areas and panels	\$ 80.00
5	Refocus and adjust headlamps assy	\$ 70.00
6	Remove and replace aircon condenser and pipes	\$ 220.00
7	Remove and replace radiator assy, hoses and fan assy	\$ 220.00

250

400

30

20

20

x

x

720

Total: \$ 1,860.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Steve (LKK)
13/12/24, 11.00am
Without Prejudice
L/S
Resurvey After Spray
3

Spare Parts: \$ 7,334.40

Special Nett: \$ 140.00

Labour: \$ 1,860.00

Total: \$ 9,334.40

5,212.40

L/S - 4,169.92
= 4150.00