

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/12/2024

User ID : weedek02

Section A - Accident Details			
Registration Number	SHB8813M		
Case Reference Number	TAX/12/24/2019		
Registration Date	29/8/23		
Company Type	Strides Premier Taxi Pte Ltd		
Make	KIA		
Model	NIROPLUS		
Name of Driver	TEO SIEW GIOK		
Type of Accident	Head to Rear		
Accident Date and Time	7/12/24 10:00 PM		
Accident Reported Date and Time	9/12/24 1:30 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number	ACGJ24120026		
Special Instruction to ARC,if any	DAMAGE TO THE LEFT FRONT OF TAXI		
Prepared Date and Time	9/12/24 2:00 PM		
Chassis Number			
Mileage			
Work Shop			
Repair Completion Date and Time			

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$378.00	\$0.00
Total Spare Part Cost	\$2,645.62	\$0.00
Total Other Cost	\$120.00	\$0.00
TOTAL COST	\$3,819.62	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date	09/12/2024 2:05 PM	
Signature	<div><div></div><div>x</div></div>	<div><div></div><div>x</div></div>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve (LKK)  
12/12/24, 3.00pm  
Without Prejudice  
P/P  
Resurvey Before Spray  
2 days

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/12/2024

User ID : weedek02

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR FRONT PORTION			\$676.00				200		
Total Labour			\$676.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO RESPRAY FRONT BUMPER			\$378.00				200		
Total Spray Painting & Panel Beating			\$378.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO CHECK WIRING AND SYSTEM FUNCTION			\$120.00				30 Nec		
Total Other Costs			\$120.00						
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			CLIPS PIECE, FRT BUMPER	10.00	\$4.80	35.00	\$31.20	Replace	/ Nec
		86551DB000	BRACKET-FR BUMPER SIDE,LH	1.00	\$13.80	10.00	\$12.42	Replace	?
		92207DB000	LAMP ASSY-DAY RUNNING LIGHT,LH	1.00	\$711.85	10.00	\$640.67	Replace	?
		86563DB000	COVER-FR BUMPER FOG LAMP,LH	1.00	\$110.40	10.00	\$99.36	Replace	/ Cut
		92101G5520	LAMP ASSY-HEAD,LH	1.00	\$1,081.00	10.00	\$972.90	Replace	?
		86512DB000	COVER-FR BUMPER,LWR	1.00	\$343.85	10.00	\$309.47	Replace	x nn
		86511DB000	COVER-FR BUMPER UPR	1.00	\$644.00	10.00	\$579.60	Replace	/ DEF
Total					\$2,909.70		\$2,645.62		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									