



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: TEO SWEE KEONG			Ref: CS/FCI24120194/Tnh3e2(N) Date: 14/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8411J	Veh. Inspected	SME 2872G	
Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
Claim No.	D24010886MFCT	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	12/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC 1.6	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MRHFC5650JT001358	Colour	BLACK	
Odometer	97597 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	MICHELIN	6 mm	
L/H Front Tyre	215/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2024	Inspection Date	16/12/2024	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		