



SERVICE PRE-INVOICE

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer: CU0025689 / MS FIRST CAPITAL
Chassis No: MRHFC5650JT001358
License No: SME2872G
Mileage: 93179
Engine No: R16B25501588

Document No: SVO24046969
Printed By: SHNG
Order Date: 16. December 2024
Order Time: 3:36:20 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:MOHAMED NOOR BIN ABDULLAH OWNER INSURER:TOKIO ACC DATE:11/12/2024 SURVEYED BY:TAUFIKH DATE:16/12/2024 REF NO: TP INSURER:FIRST CAP TP VEH:SHC8411J SUPPLEMENTARY PART						
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	39.14	474.06
71130-TEA-T00	BEAM COMPFR.BUMPER	1	418.60	25	313.95	28.26	342.21
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	91.40	25	68.55	6.17	74.72
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	91.40	25	68.55	6.17	74.72
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.70	8.50
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.70	8.50
91505-TM8-003	CLIP,BUMPER	16	2.30	25	27.60	2.48	30.08
71121-TEA-T02	BASE,FR.GRILLE CHROME	1	89.20	25	66.90	6.02	72.92
71125-TEA-T01	MOLDINGFR.GRILLE	1	121.40	25	91.05	8.19	99.24
75700-TBA-A00	EMBLEM	1	18.20	25	13.65	1.23	14.88
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.28	3.43
33100-TEC-306	HEADLIGHT ASSY,R.	1	708.80	25	531.60	47.84	579.44
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	4.05	49.05
80100-TBA-A02	CONDENSER ASSY	1	704.40	25	528.30	47.55	575.85
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	41.66	504.56
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	44.10	25	33.07	2.98	36.05
71506-TEX-Y00	COVERRR.TOWING HOOK	1	9.50	25	7.12	0.64	7.76
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	199.30	25	149.47	13.45	162.92
66100-TEC-307ZZ	PANEL SETRR.	1	294.30	25	220.72	19.86	240.58
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	32.40	25	24.30	2.19	26.49
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	32.40	25	24.30	2.19	26.49
74940-SZW-003	BUZZER ASSYSMART	1	66.90	25	50.17	4.52	54.69
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE	1	103.60	25	77.70	6.99	84.69
75722-TBA-A00	EMBLEM SETRR.	1	14.30	25	10.72	0.96	11.68
75725-TEA-T01	EMBLEMRR.	1	13.30	25	9.97	0.90	10.87
	SUM PARTS:				3,279.26	295.12	3,574.38
BOSUN	1466 SUNDRIES	1	50.00		50.00	4.50	54.50
BML01I	1466 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	220.00		220.00	19.80	239.80
BMA01D	1466 REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)	1	580.00		580.00	52.20	632.20
BMC01D	1466 REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)	1	530.00		530.00	47.70	577.70



SERVICE PRE-INVOICE

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer: CU0025689 / MS FIRST CAPITAL
Chassis No: MRHFC5650JT001358
License No: SME2872G
Mileage: 93179
Engine No: R16B25501588

Document No: SVO24046969
Printed By: SHNG
Order Date: 16. December 2024
Order Time: 3:36:20 PM
Service Advisor: NG SIN HAI

BKBH01S	1466	1	1,950.00	1,950.00	175.50	2,125.50
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.					
BP03R	1466	1	1,560.00	1,560.00	140.40	1,700.40
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)					
BOJSE	1466	1	110.00	110.00	9.90	119.90
	SEALANT FOR REAR END PANEL					
BML02I	1466	1	220.00	220.00	19.80	239.80
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)					
BA02R	1466	1	220.00	220.00	19.80	239.80
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)					
BC012R	1466	1	580.00	580.00	52.20	632.20
	RESET VEHICLE SMART ENTRY SYSTEM					
BC011R	1466	1	580.00	580.00	52.20	632.20
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA					
BMI03D	1466	1	650.00	650.00	58.50	708.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)					
BKRP02M	1968	1	2,600.00	2,600.00	234.00	2,834.00
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.					
BP05R	1847	1	3,120.00	3,120.00	280.80	3,400.80
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)					
BOBC	1847	1	480.00	480.00	43.20	523.20
	BODY UNDERSIDE COATING (N)					

SUM LABOUR: 13,450.00 1,210.50 14,660.50

TOTAL SGD 16,729.26 1,505.62 18,234.88

Total Payable (SGD) 18,234.88

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer: CU0025689 / MOHAMED NOOR
Chassis No: MRHFC5650JT001358
License No: SME2872G
Mileage: 93179
Engine No: R16B25501588

Document No: SVO24046969
Printed By: SHNG
Order Date: 16. December 2024
Order Time: 3:36:20 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	9% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER de✓	1	617.20	25	462.90	41.66	504.56
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER de✓	1	44.10	25.	33.07	2.98	36.05
71506-TEX-Y00	COVERRR.TOWING HOOK de ✓	1	9.50	25.	7.12	0.64	7.76
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER bt✓	1	199.30	25.	149.47	13.45	162.92
66100-TEC-307ZZ	PANEL SETRR. bt ✓	1	294.30	25.	220.72	19.86	240.58
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE bt✓	1	32.40	25	24.30	2.19	26.49
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE bt✓	1	32.40	25	24.30	2.19	26.49
74940-SZW-003	BUZZER ASSYSMART cra✓	1	66.90	25.	50.17	4.52	54.69
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE cra✓	1	103.60	25	77.70	6.99	84.69
75722-TBA-A00	EMBLEM SETRR. nec ✓	1	14.30	25.	10.72	0.96	11.68
75725-TEA-T01	EMBLEMRR. nec✓	1	13.30	25.	9.97	0.90	10.87
SUM PARTS:					1,070.44	96.34	1,166.78
TOTAL SGD					1,070.44	96.34	1,166.78

Total Payable (SGD)

1,166.78

GST Amount is calculated from individual line(s)

