

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120195/EPA3Q2  
Date: 06/06/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582\_01  
Claimant Vehicle No : FBL9312D Insured Vehicle No : SLF2976Y  
Date of Loss: 10/12/2024 Nature of Claim: TP Claim No: MFL2024D0014744

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBL9312D  
Make & Model: YAMAHA TMAX530, 530cc CVT ABS Engine No: J409E066563  
Reg. Date: 28/03/2016 (Man. Year: 2016) Chassis No: JYASJ099000017145  
Colour: Black Odometer: 34144 km  
Engine Capacity: 530 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R15 Rear Tyre Size: 160/60 R15  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 0 mm Rear Right Side: Michelin 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------------|------------|------------|------------|--------|
| Parts                                    | 5,532.00   | 4,762.80   | 769.20     | 13.90  |
| Miscellaneous Items                      | 0.00       | 0.00       | 0.00       |        |
| Labour                                   | 1,105.00   | 635.00     | 470.00     | 42.53  |
| Paintwork Labour                         | 0.00       | 0.00       | 0.00       |        |
| Towing                                   | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)             | 6,637.00   | 5,397.80   | 1,239.20   | 18.67  |
| Approved Total (Overridden) (S\$)        |            | 5,000.00   |            |        |
| (S\$)                                    | 6,637.00   | 5,000.00   | 1,637.00   | 24.66  |
| + GST 9.00/9.00% (S\$)                   | 597.33     | 450.00     | 147.33     | 24.66  |
| Nett Amount (S\$)                        | 7,234.33   | 5,450.00   | 1,784.33   | 24.66  |
| + Loss of Use (3.0 x S\$20.00/day) (S\$) |            | 60.00      |            |        |
| + Doc/Search Fee (S\$)                   |            | 27.25      |            |        |
| Nett Liability (S\$)                     |            | 5,537.25   |            |        |

INSPECTION

Date of Assignment: 13/12/2024  
Date Inspected: 13/12/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)  
Industrial City  
Singapore 533758  
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                |
| Part Source:  | (Last Synchronised: 30 May 2025)                                                                                                                                             |                                                                |
| Parts:        | N/A                                                                                                                                                                          | YAMAHA TMAX530 530cc CVT ABS (Model not available in database) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| Print Code:   | (Unsubmitted, no print-code for FBL9312D)                                                                                                                                    |                                                                |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition | Repairer's | Amount       |
|-----|-----|----------|------------------------------------------|-----------|------------|--------------|
| 1   | 1   |          | *BELLY PAN INNER                         | Cut       | 51.00 F    | *51.00 FL    |
| 2   | 1   |          | *BOARD FOOTREST RH                       | Cut       | 248.00 F   | *248.00 FL   |
| 3   | 1   |          | *BODY COWLING                            | Cut       | 157.00 F   | *157.00 FL   |
| 4   | 1   |          | *BOX REAR ALUMINIUM 45LITRE (ZEDGE)      | Cut       | 372.00 F   | *372.00 FL   |
| 5   | 1   |          | *BRACKET 1                               | Bent      | 16.00 F    | *16.00 FL    |
| 6   | 1   |          | *COVER GENERATOR                         | Cut       | 14.00 F    | *14.00 FL    |
| 7   | 1   |          | *COVER SIDE LOWER RH                     | Cut       | 147.00 F   | *147.00 FL   |
| 8   | 1   |          | *COVER SIDE LOWER TAIL RH                | Cut       | 239.00 F   | *239.00 FL   |
| 9   | 1   |          | *COVER SIDE TAIL LH                      | Cut       | 212.00 F   | *212.00 FL   |
| 10  | 1   |          | *COVER SIDE TAIL RH                      | Cut       | 214.00 F   | *214.00 FL   |
| 11  | 1   |          | *COVER TRANSMISSION (RH)                 | Cut       | 51.00 F    | *51.00 FL    |
| 12  | 1   |          | *DAMPER                                  | Necessary | 4.00 F     | *4.00 FL     |
| 13  | 1   |          | *DAMPER (BOARD FOOTREST 2)               | Necessary | 3.00 F     | *3.00 FL     |
| 14  | 1   |          | *DAMPER 1                                | Necessary | 9.00 F     | *9.00 FL     |
| 15  | 1   |          | *DAMPER 2 (BOARD FOOTREST 2)             | Necessary | 5.00 F     | *5.00 FL     |
| 16  | 1   |          | *DAMPER 3                                | Necessary | 6.00 F     | *6.00 FL     |
| 17  | 1   |          | *DAMPER 3 (BOARD FOOTREST 2)             | Necessary | 12.00 F    | *12.00 FL    |
| 18  | 1   |          | *DAMPER 4 (BOARD FOOTREST)               | Necessary | 2.00 F     | *2.00 FL     |
| 19  | 1   |          | *DAMPER COVER SIDE CENTRE                | Necessary | 5.00 F     | *5.00 FL     |
| 20  | 1   |          | *DAMPER COVER TRANSMISSION               | Necessary | 6.00 F     | *6.00 FL     |
| 21  | 1   |          | *DAMPER COVER TRANSMISSION 2             | Necessary | 5.00 F     | *5.00 FL     |
| 22  | 1   |          | *DAMPER COVER TRANSMISSION 3             | Necessary | 3.00 F     | *3.00 FL     |
| 23  | 1   |          | *DAMPER LOCATING 2                       | Necessary | 8.00 F     | *8.00 FL     |
| 24  | 1   |          | *EMBLEM                                  | Necessary | 29.00 F    | *29.00 FL    |
| 25  | 1   |          | *EMBLEM 3D                               | Necessary | 85.00 F    | *85.00 FL    |
| 26  | 1   |          | *FOOTBOARD FRONT LH                      | Cut       | 248.00 F   | *248.00 FL   |
| 27  | 1   |          | *FOOTREST REAR RH ASSY                   | Broken    | 163.00 F   | *163.00 FL   |
| 28  | 1   |          | *FOOTREST REAR SET (AFTERMARKET)         | Cut       | 93.00 F    | *93.00 FL    |
| 29  | 1   |          | *LEVER BRAKE LH                          | Cut       | 99.00 F    | *99.00 FL    |
| 30  | 1   |          | *MIRROR SET (AFTERMARKET)                | Cut       | 54.00 F    | *54.00 FL    |
| 31  | 1   |          | *MOLE, SIDE COVER                        | Cut       | 176.00 F   | *176.00 FL   |
| 32  | 1   |          | *MUFFLER (ARROW)                         | Cut       | 1,860.00 F | *1,860.00 FL |
| 33  | 1   |          | *PANEL 1 (LH LOWER)                      | Cut       | 102.00 F   | *102.00 FL   |
| 34  | 1   |          | *PLATE 1                                 | Cut       | 26.00 F    | *26.00 FL    |
| 35  | 1   |          | *PLATE BIG FOOT SIDE STAND               | Cut       | 78.00 F    | *78.00 FL    |
| 36  | 1   |          | *PROTECTOR EXHAUST (R&G) ROUND 4.5/5INCH | Cut       | 164.00 F   | *164.00 FL   |
| 37  | 2   |          | *SLIDER FLOOR BOARD (R&G)<br>(RH & LH)   | Cut       | 326.00 F   | *326.00 FL   |
| 38  | 1   |          | *STAND MAIN                              | Repair    | 240.00 F   | *- FL        |

F=Franchise part. L=ListItemDisc.

|                                                    |          |          |
|----------------------------------------------------|----------|----------|
| Sub Total (\$\$)                                   | 5,532.00 | 5,292.00 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00     | 529.20   |
| Total Parts (\$\$)                                 | 5,532.00 | 4,762.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                       | Particulars                                              | Lab.Type | Repairer's | Amount |
|--------------------------|----------------------------------------------------------|----------|------------|--------|
| <u>Labour Items</u>      |                                                          |          |            |        |
| 1                        | LABOUR FOR DISMANTLING & INSTALLATION OF PARTS.          | New      | 1,020.00   | 550.00 |
| 2                        | TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 - ONE WAY TOWING. | New      | 85.00      | 85.00  |
| Gross Labour Cost (\$\$) |                                                          |          | 1,105.00   | 635.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >