



Supplementary

Estimate No. : **b1 70264**
Date Estimated : **24/06/2024**
Prepared By : **Yap Mee Key**

Page No. :

- ESTIMATE REPAIR FOR -

Lee Mui Hong
106 Westwood Crescent

Singapore 648797

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SJL8848L	WBAKR020600S46379	18/07/2017	X5 xDrive35i	175524

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front bumper panel, bonnet, front LH fender, LH wingmirror assembly, front shock absorber, LH trim air duct, LH grille side closed, LH cover spray nozzle, lower trim panel, set of dummy trims, LH headlight support, LH module carrier, front LH reinforcement side panel, front LH front section wheel arch cover, front LH wheel well trim, LH LED fog light include making good the front LH door, rear LH door and carrying out other necessary repairs caused by the accident	3,400.00		3,400.00
* To respray bonnet, front bumper, front LH fender, front LH wheel arch trim, front LH door, rear LH door and LH wingmirror cover	6,114.00		6,114.00
* To replace surround view camera include programming and conducting checks for proper function	266.00		266.00
** To replace wheel rim include balancing (x1)	94.00		94.00
** To check steering geometry and conduct wheel alignment in accordance with BMW specifications (x1)	531.00		531.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET	3.10	10.00	0.00	31.00
# ALLOY RIM 10JX20 DOUBLE SPK 300	2,200.00	1.00	0.00	2,200.00
# TRIM AIR DUCT LH	108.25	1.00	0.00	108.25
# FRT BUMPER PANEL PRIMED (PMA/CAM/SR)	1,747.70	1.00	0.00	1,747.70
# SET OF DUMMY TRIMS (GEN 5.7 x)	56.95	1.00	0.00	56.95

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W



Performance Motors

BMW Dealer



Supplementary

# FRT LH FRT SECTION WHEEL ARCH COVER	204.80	1.00	0.00	204.80
# BLIND RIVET	1.45	10.00	0.00	14.50
# REPAIR KIT CABLE EXTERIOR MIRROR	76.60	1.00	0.00	76.60
# LH LED MODULE TURN INDICATOR	949.60	1.00	0.00	949.60
# BLIND RIVET	1.45	2.00	0.00	2.90
# SURROUND VIEW CAMERA	736.95	1.00	0.00	736.95
# LABEL COOLANT 675+/-10G	26.85	1.00	0.00	26.85

SUPPLEMENTARY ITEMS

Total Labour :	10,405.00
Total Parts :	6,156.10
Total Labour & Parts (before GST) :	16,561.10

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

