



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

Steve (LKK)

19/12/24, 10.12.24

90-N1 AL, Excess - ?

PIP

M ReL Sky

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunos Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Ms Phua Mei Ching Serene 536 Serangoon North Avenue 4 #09-203 Singapore 550536
	Document No. 0	
	Document Date 13/12/2024	Mobile: 91792899

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXVH71R	AEXSBW S1	28/12/2021	SMQ4868T	0	35519	72/OD/SMQ4868T

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTNB23HK103108504	A25A5667066	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC24P00240600 ACC DATE:13.12.2024 DRIVE IN:13.12.2024 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				80 / 50.00
2	Z	BP-MPS CRIMEN'S PROCESSING FEES				✓ 12.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL FRONT BUMPER SENS OR				✓ 158.40
4	B	BP-LAB2 CHECK WIRING SYSTEM				✓ 107.71
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				✓ 158.40
6	B	BP-MECH2 TO CONDUCT ADJUSTMET ON FRONT RADAR SENS OR				✓ 158.40
7	S	BP-SUBLET SUPPLY FRONT NUMBER PLATE				80 / 80.00
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				658-601267.20
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				524.80 1049.60
10	1	S52535-06240 RETAINER, FR BUMPER	1.00	132.20	30.00	92.54
11	2	S52536-06240 RETAINER, FR BUMPER	1.00	132.20	30.00	92.54
12	3	T52611-33360 ABSORBER, FR BUMPER	1.00	141.20	30.00	98.84
13	4	S52131-06211 REINFORCEMENT, FR BU	1.00	551.50	30.00	386.05

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.		Customer Details				
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600		S1000026 / ICECICS		Ms Phua Mei Ching Serene 536 Serangoon North Avenue 4 #09-203 Singapore 550536 Mobile: 91792899				
		Document No. 0						
		Document Date 13/12/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	AXVH71R	AEXSBW S1	28/12/2021	SMQ4868T	0	35519	72/OD/SMQ4868T	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTNB23HK103108504		A25A5667066	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
14	5	T52119-3T971	COVER, FR BUMPER	1.00	880.40	30.00	616.28	
15	6	T89348-33210	RETAINER, ULTRASONIC	2.00	21.40	30.00	29.96	
16	7	T53395-33040	SEAL, HOOD TO FR END	1.00	91.80	30.00	64.26	
17	8	T53102-33490	GRILLE SUB-ASSY,	1.00	653.00	30.00	457.10	
18	9	T52114-33630	BRACKET, FR BUMPER	1.00	159.80	30.00	111.86	
19	0	T52712-33100	MOULDING, FR BUMPER	1.00	197.90	30.00	138.53	
20	1	T52713-33100	MOULDING, FR BUMPER	1.00	197.90	30.00	138.53	
21	2	T81481-33140	COVER, FOG LAMP, RH	1.00	335.10	30.00	234.57	
22	3	T81482-33130	COVER, FOG LAMP, LH	1.00	335.10	30.00	234.57	
23	4	L75392-35220	RETAINER, OUTSIDE	8.00	5.60	30.00	31.36	
24	5	L90467-07220	CLIP	8.00	3.60	30.00	20.16	
25	6	T52127-33170	COVER, FR BUMPER	1.00	76.20	30.00	53.34	
26	7	T52128-33280	COVER, FR BUMPER	1.00	76.20	30.00	53.34	
27	8	T52533-33040	BRACKET, FR BUMPER	1.00	34.50	30.00	24.15	
28	9	T52534-33030	BRACKET, FR BUMPER	1.00	34.50	30.00	24.15	
29	0	T52422-33020	PAD, FR BUMPER, RH	1.00	28.30	30.00	19.81	
30	1	T53122-33110	MOULDING, RADIATOR	1.00	177.30	30.00	124.11	
31	2	T53123-33150	MOULDING, RADIATOR	1.00	230.00	30.00	161.00	
32	3	T53124-33170	MOULDING, RADIATOR	1.00	230.00	30.00	161.00	
33	4	T90975-02161	EMBLEM, SYMBOL	1.00	1109.80	30.00	776.86	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Ms Phua Mei Ching Serene 536 Serangoon North Avenue 4 #09-203 Singapore 550536 Mobile: 91792899			
			Document No. 0					
			Document Date 13/12/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	AXVH71R	AEXSBW S1	28/12/2021	SMQ4868T	0	35519	72/OD/SMQ4868T	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTNB23HK103108504		A25A5667066	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
34	5	T53101-33640 GRILLE SUB-ASSY, nn			1.00	1016.20	30.00	711.34
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 7,897.96		
Please acknowledge receipt of vehicle		Parts		4,856.25		GST 9.00% 710.82		
		Labour		2,961.71				
		Sublet		80.00				
		Lubrication/Fluid		0.00		Less 0.00		
		Others		0.00		Amount Due 8,608.78		

Customer Copy

The following Endorsements shall apply to this Policy:

- V0003 BREAKAGE OF GLASS IN WINDSCREEN OR WINDOW (SUN ROOF/ MOON ROOF FOR PRIVATE CAR ONLY)
- V0009 FLOOD AND OTHER SPECIAL PERILS
- V0010 24/7 ACCIDENT ASSISTANCE
- V0011 HIRE PURCHASE
- V0012 MARKET VALUE FOR THE PURPOSE OF TOTAL LOSS SETTLEMENT
- V0014 STRIKE RIOT AND CIVIL COMMOTION
- V0017 TOTAL LOSS
- V0019 YOUNG, ELDERLY OR INEXPERIENCED DRIVERS EXCESS
- V0020 NON-CANCELLATION CLAUSE
-  V0060 **WAIVER OF EXCESS CLAUSE - OWN DAMAGE CLAIM (SECTION I) FOR FIRST ACCIDENT CLAIM (INSURED AND NAMED DRIVERS ONLY) AT AUTHORISED WORKSHOP**

Subject to the following Clauses / Warranties / Endorsements / Memo attached hereto :-

OB0008 LOSS OF USE BENEFIT

Authorised Drivers for vehicle(s) with Certificate Ref.: MZ300

- a) The Insured and all the Named Drivers declared under this Policy
- b) Any other person who is driving on the Insured's order or with his / her permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car.

Limitations as to use for vehicle(s) with Certificate Ref.: MZ300

Use for social, domestic and pleasure purposes and for the Insured's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Driver details for policy **MPC24P00240600** and Risk No. **00001** as follows:

Named Drivers	Sex	Marital Status	Age	Exp	NRIC/FIN
PHUA MEI CHING SERENE	F	M	48	18	S7535290E
GOH YONG SHIAN	M	M	48	16	S7534786C

Signed for and on behalf of ECICS Limited



Authorised Signatory