



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Ms Phua Mei Ching Serene 536 Serangoon North Avenue 4 #09-203 Singapore 550536 Mobile: 91792899
	Document No. 0	
	Document Date 06/03/2025	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXVH71R	AEXSBW S1	28/12/2021	SMQ4868T	0	35519	72/OD/SMQ4868T
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTNB23HK103108504	A25A5667066	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC24P00240600 ACC DATE:13.12.2024 DRIVE IN:13.12.2024 EXCESS:NIL DATE-IN:03.03.2025 DATE SURVEY:19.12.2024 NO OF REPAIR DAYS:04 WORKING DAYS BY:LKK-STEVE AUTHORISED ON:20.12.2024				30.00
2	Z	BP-MPS MERIMEN'S PROCESSING FEES				12.00
3	S	BP-SUBLET SUPPLY FRONT NUMBER PLATE	0263			80.00
4	B	BP-AI2 DRILL HOLE AND INSTALL FRONT BUMPER SENS OR	*			158.40
5	B	BP-AI2 CHECK WIRING SYSTEM	*			107.71
6	B	BP-AI2 TO RESET ECU AND REPROGRAMME	*			158.40
7	B	BP-AI2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR	*			158.40
8	B	BP-AI2 REPLACE ACC DAMAGED PARTS	*			633.60
9	B	BP-AI2 RESPRAY ACC AFFECTED AREAS	*			524.80
10	1	T52119-3T971 COVER, FR BUMPER	1.00	880.40	30.00	616.28
11	2	T89348-33210 RETAINER, ULTRASONIC	2.00	21.40	30.00	29.96
12	3	T53395-33040 SEAL, HOOD TO FR END	1.00	91.80	30.00	64.26
13	4	T53102-33490 GRILLE SUB-ASSY,	1.00	653.00	30.00	457.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Ms Phua Mei Ching Serene 536 Serangoon North Avenue 4 #09-203 Singapore 550536 Mobile: 91792899
	Document No. 0	
	Document Date 06/03/2025	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXVH71R	AEXSBW S1	28/12/2021	SMQ4868T	0	35519	72/OD/SMQ4868T
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTNB23HK103108504	A25A5667066	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	5	T52114-33630 BRACKET, FR BUMPER	1.00	159.80	30.00	111.86
15	6	T81481-33140 COVER, FOG LAMP, RH	1.00	335.10	30.00	234.57
16	7	L75392-35220 RETAINER, OUTSIDE	8.00	5.60	30.00	31.36
17	8	L90467-07220 CLIP	8.00	3.60	30.00	20.16
18	9	T53123-33150 MOULDING, RADIATOR	1.00	230.00	30.00	161.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	3,589.86
	Please acknowledge receipt of vehicle	Parts 1,726.55 Labour 1,783.31 Sublet 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00%	323.09
			Less	0.00
			Amount Due	3,912.95

Company Copy