

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01,
SGX Centre Two,
Singapore 068807

Attn : Motor Claims Department
Tel : 6827 2888
Fax : 6827 7800

Estimate bill : TT 46 / 24 / TP / WT

Registration No : SME44T

Make / model : Hyundai Elantra

Mileage :

Date : 21 / 12 / 2024

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : FBW114K AND SME44T ALONG
SERANGOON AVENUE 3 (AMARANDA GARDENS OUTSIDE THE GUARD HOUSE) ON 07 DECEMBER 2024
AT ABOUT 1630HRS.

1pc	Front RH fender	\$	969.00	X
1pc	Front RH fender cowling	\$	99.00	X
1pc	Front RH door	\$	1,231.00	✓
1pc	Front RH door side mirror assy	\$	776.00	X
1pc	Front RH door weather strip	\$	166.00	X
	Sub A total :	\$	3,241.00	
	Less 20% discount :	\$	648.20	
	A total :	\$	2,592.80	

Remove and transfer front RH Fender.

Remove and transfer front RH door necessary attachment spare part items.

Remove and refit front RH fender, front RH fender cowling, front RH door, front RH door side mirror assy, front RH door weather strip.

Putty / primer application, spray painting front RH fender, front RH door, front RH door side mirror.

Grand final amount :

\$ 3,892.80

Tropical Tech Automobile Services

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(Authorised Signature)
William Tan