

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg


MR CHANG SEAFOOD TRADING
5 MANDAI LINK #10-08
MANDAI FOODLINK
SINGAPORE 728654

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SMH5510R (Lonpac)
OUR REF : TP6736
VECHICLE NO : GBJ3597Z
MAKE/MODEL : Mit Canter
DATE OF ACCIDENT : 13 Dec 24

SURVEY BY

DATE : 13.Dec.24

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
2	PCS TAILAMP ASSY	220.00	440.00	cut
2	PCS TAILAMP BRACKETS	250.00	500.00	bt 400
1	PC TAILBOARD		4,500.00	bt 2800
3	PCS TAILBOARD HINGE	160.00	320.00	bt
1	PC TAILBOARD "FUSO" STICKER		110.00	rec
1	PC REAR NUMBER PLATE BRACKET		260.00	bt
1	PC AD BLUE CONTAINER		7,007.00	de 4100
1	PC AD BLUE PUMP		3,800.00	bt 2400
1	PC AD BLUE SENSOR		1,600.00	xnn
1	PC AD BLUE CONTAINER BRACKET		980.00	bt 720
1	PC REAR FENDER INNER SHIELD L/H		210.00	de
1	PC REAR MUD FLAP L/H		190.00	xnn
1	PC REAR EXHAUST		9,800.00	bt 4920
4	PCS REAR EXHAUST MOUNTING	188.00	752.00	bt
1	PC EXHAUST BRACKET		130.00	bt
1	PC EXHAUST CONTROLLER SENSOR		1,850.00	xnn
1	PCS EXHAUST HEATER SENSOR	1,950.00	5,850.00	bt 1950
1	PCS O2 SENSOR	360.00	720.00	lpc-bro 360
1	PC EXHAUST CENTER PIPE		5,600.00	bt 2500
1	PC REAR SPRING		1,800.00	xnn
2	PCS REAR SPRING BRUSH	650.00	1,300.00	xnn
			S\$ 47,719.00	22372
	LESS 10%		4,771.90	
			S\$ 42,947.10	20134.80
1	PC TAILBOARD "70KM/HR" STICKER		S\$ 30.00	S/ NETT
1	PC TAILBOARD 6 PAX STICKER		30.00	"
1	PC REAR NUMBER PLATE		45.00	"
1	PC REAR CARRIER ALUMINUM		900.00	" 600
			S\$ 1,005.00	



進友成汽車服務有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

TO TRANSFER TAILBOARD

S\$ 100.00⁶⁰

TO DISMANTLE AND REFIX AD BLUE

400.00²⁰⁰

TO DISMANTLE AND REFIX EXHAUST

200.00¹⁵⁰

TO COMPUTER RESET

600.00²⁰⁰ ✓

TO CHECK WIRING FUNCTION

30.00 ✓

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

150.00⁴⁰

LABOUR CHARGES

600.00⁵⁰⁰

TO PUTTY AND SPRAY PAINTING CHARGES

1680 600.00⁴⁵⁰
⁵⁰⁰

S\$ 46,632.10

SIN DOLLARS: FORTY-SIX THOUSAND SIX HUNDRED THIRTY-TWO DOLLARS ONLY TEN ONLY.

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Tanfiah 97495741/62563581
w/ 17/12/24 4200

C/S Resurvey after repair
Tanfiah C LKK auto.

5 days

20134.80

705

1680

22519.80

4/5 18000

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: