



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS3/INC24120214/Enh3m4
75 BRAS BASAH ROAD	Date:	19/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	GBK 1798T	Veh. Inspected	SNA 6382L
Policy No.	-	Coverage	0
Claim No.	MT/1306947-001	Excess	\$0.00
Assign From	CHARLOTTE CHEW	Assign Date	11/12/2024

2. Vehicle Details

Make & Model	AUDI A4	C.C	1984
Engine No.	CVK060738	Year of Reg.	03/07/2018
Chassis No.	WAUZZZF41JA159954	Colour	BLUE
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40ZR18	LANDSPIDER	5
L/H Front Tyre	245/40ZR18	LANDSPIDER	5
R/H Rear Tyre	245/40ZR18	LANDSPIDER	5
L/H Rear Tyre	245/40ZR18	LANDSPIDER	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

5. General Information

Accident Date	02/12/2024	Inspection Date	11/12/2024 (14:32)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.