

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 16-Dec-24

INSURANCE: TII

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 1819 Z

Description	Qty	List Price	Amount
Radiator Grille Emblem <i>Cut</i>	1	\$ 88.00	\$ 88.00
Radiator Grille <i>broken</i>	1	\$ 1,409.10	\$ 1,409.10
Flap Assy Active Air Upper, (LH/RH) <i>broken</i>	2	\$ 824.60	\$ 1,649.20
Speaker Assy-VESS <i>HL</i>	1	\$ 554.40	\$ 554.40
Unit Assy-SMART CRU (Radar Sensor) <i>main body broken</i>	1	\$ 3,061.40	\$ 3,061.40
Flap Assy Active wire <i>HL</i>	1	\$ 765.30	\$ 765.30
Front Number Plate garnish <i>SVC</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>broken</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HL</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>SVC</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>SVC</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH/RH) <i>HL</i>	2	\$ 186.50	\$ 373.00
Front Bumper Towing Cover <i>HL</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>SVC</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HL</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner <i>HL</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>main body grille</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>SVC</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>HL</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>HL</i>	2	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>HL</i>	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH/RH) <i>HL</i>	2	\$ 65.30	\$ 130.60
Front Bumper Clips 10 pcs <i>HL</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH/RH) <i>HL</i>	2	\$ 186.90	\$ 373.80

✓

✓

✓

✗

✓ 2910.90

✗

✗

✓

✗

✗

✗

✗

✗

✗

✗

✗

✓

✗

✗

✗

✗

✗

✓

✗

Front bumper air duct (LH/RH) <i>huc</i>	2	\$ 153.80	\$ 307.60	X
Day Light ,LH <i>huc</i>	1	\$ 642.50	\$ 642.50	X
Day Light , RH <i>huc</i>	1	\$ 642.50	\$ 642.50	X
BUZZER ASSY - PIEZO (LH) <i>huc</i>	1	\$ 388.00	\$ 388.00	X
Headlamp Support Panel Assy <i>huc</i>	1	\$ 1,139.30	\$ 1,139.30	X
Headlamp(LH/RH) <i>crack 2110-30x2</i>	2	\$ 3,987.30	\$ 7,974.60	✓ 4220.60
Horn Unit (LH/RH) <i>huc</i>	2	\$ 72.80	\$ 145.60	X
Radiator Inverter <i>huc</i>	1	\$ 884.80	\$ 884.80	X
Radiator <i>huc</i>	1	\$ 710.50	\$ 710.50	X
Radiator fan blower motor assy <i>huc</i>	1	\$ 1,459.60	\$ 1,459.60	X
Radiator Air Guard (LH/RH) <i>huc</i>	2	\$ 76.40	\$ 152.80	X
Radiator Air Guard, Upr (LH/RH) <i>huc</i>	2	\$ 127.50	\$ 255.00	X
Aircon Condenser <i>huc / puncture</i>	1	\$ 663.60	\$ 663.60	✓
Rear Bumper <i>crack</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Reinforcement <i>src</i>	1	\$ 394.80	\$ 394.80	X
Rear Bumper Reinforcement Bracket (LH/RH) <i>huc</i>	2	\$ 188.10	\$ 376.20	X
Antenna Assy-SMARTK outer <i>mostly broke</i>	1	\$ 689.50	\$ 689.50	✓
Rear Bumper Centre Moulding Assy <i>crack</i>	1	\$ 451.25	\$ 451.25	✓
Rear Bumper Lower Centre Moulding Assy <i>src</i>	1	\$ 47.50	\$ 47.50	X
Rear Bumper Stay <i>huc</i>	1	\$ 138.10	\$ 138.10	X
Rear Bumper Side retainer (LH/RH) <i>huc</i>	2	\$ 85.80	\$ 171.60	X
Rear Bumper Cover Clips <i>huc</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Under Centre <i>mostly broke</i>	1	\$ 123.85	\$ 123.85	X ✓
Rear Bumper Side Under(LH/RH) <i>huc</i>	2	\$ 123.10	\$ 246.20	X
Rear Bumper Reflector Lamp(LH/RH) <i>huc</i>	2	\$ 82.90	\$ 165.80	X
Rear Bumper Towing Cover <i>src</i>	1	\$ 98.80	\$ 98.80	X
Rear Bumper Reserve Light (Parking Brake Light) <i>src</i>	1	\$ 328.60	\$ 328.60	✓
Licence Lamp <i>huc</i> <i>broke</i>	1	\$ 193.53	\$ 193.53	X
Licence Lamp WIRE <i>huc</i>	1	\$ 135.80	\$ 135.80	X
Rear Panel <i>huc</i>	1	\$ 532.00	\$ 532.00	X
Antenna Assy - TRUNK <i>huc</i>	1	\$ 689.50	\$ 689.50	X

Rear Panel Garnish <i>HL</i>	1	\$ 346.80	\$ 346.80
SUB TOTAL			\$ 33,306.63
LESS 20%			\$ 6,661.33
DISCOUNTED TOTAL			\$ 26,645.30
<i>Rev</i> Front Number Plate <i>HL</i> SN	1	\$ 25.00	\$ 25.00
<i>Rev</i> Front No Plate Trim Cover <i>SR</i> SN	1	\$ 30.00	\$ 30.00
COOLANT <i>HL</i> SN	1	\$ 45.00	\$ 45.00
Rear Bumper Reverse Sensor <i>DL</i> SN	1	\$ 180.00	\$ 180.00
SUB TOTAL			\$ 280.00
Labour Charge			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,200.00	\$1,200.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$4,050.00
ESTIMATE TOTAL			\$ 30,975.30

X

13,887.40

11,109.92

451-

X

225.00

800/-

700/-

30/-

40/-

HL

30/- HL

80/-

150/-

1800.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to information

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17/12/2024 e 1300m

HLA Actual 10

4/5 km 4 dgs.

[Signature]

LKK Auto

13,134.92

4/5 10,1500/-

[Signature]

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SHA1819Z
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEKU376821
Chassis No.:	KMHC851CVKU141145
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,921.00
Original Registration Date:	01 Mar 2019
First Registration Date:	01 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$11,890.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2027
PARF Rebate Amount:	\$8,323.00

Intended COE Rebate Details

COE Expiry Date:	28 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,420.00
COE Rebate Amount:	\$5,530.00
Total Rebate Amount:	\$13,853.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Dec 2024

OK