

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JOANNE TAN

Date: 10/08/2023

PRELIMINARY ADVICE

Vehicle No	SJM 9954B	Accident Date	04/05/2023
Make	-	Policy No.	D23001545MFBP
Assignment Date	08/05/2023	Excess	-
Inspection Date	08/05/2023	Est. Duration of Repair	11

Inspected At: N-51 AUTOMOTIVE PL
2 KAKI BUKIT AVE 2

#01-17 KAKI BUKIT AUTOHUB

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$16,988.80
Revised Estimate Amount:	\$7,000.00
"Check" Items Amount	\$0.00
Total	\$0.00
Lump Sum Repair	\$7,000.00

Total Loss Consideration

Book Value	\$0.00
Market Value	\$9,000.00
COE / PARF Rebate	\$1,827.00
Salvage Value	\$0.00
Margin for Repair	\$7,173.00

Remarks

- ☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ☒ Other comments: The above survey was conducted on a "Without Prejudice" basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and