

From: _____ Date: _____
 Estimator: _____
 OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV
 To in ~~Service~~ Vehicle No: _____
 at Work / ~~Location~~ / _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____

 (Policy Condition)

	
N/S	O/S

Vehicle: IN / OUT

R: 225/SSRI

The U/C / Chassis frame / Body Structure affected due to collision.

3	Others	
---	--------	--

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0930/2024/EQ
DATE : 17-Dec-24
WIP : 42037

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR THAM WAI LEONG
ADDRESS : 317 TELOK KURAU ROAD
SINGAPORE 423865

TELEPHONE : HP +65 98318781
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800079954-06
VEHICLE NO : **SMC 5466 L**
MODEL CODE : AUDI A6 1.8 TFSI S TRONIC
MODEL YEAR : 7/7/2018
ENGINE NO : CYG 023417
CHASSIS NO : WAUZZZ4GXJN039737
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Dec-24
PLACE OF ACCIDENT : 53 SIMS PL, BLOCK 53, SINGAPORE 380053
BLOCK 53 SIMS PLACE CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 5466 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00 500	
3	TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER.	\$	2,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 4,372.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 5466 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 3,903.00	+
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 608.00	+
3	FRONT BUMPER FIXING PARTS	1	\$ 61.00	+
4	FRONT BUMPER SECURING STRIP - LH / RH <i>3 new</i>	2	\$ 117.00	+
5	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 160.00	+
6	FRONT BUMPER ADAPTER - RH <i>3 new</i>	1	\$ 48.00	+
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 266.00	+
8	FRONT BUMPER SPOILER - LOWER <i>Repair new</i>	1	\$ 310.00	+
9	FRONT SPOILER <i>Repair</i>	1	\$ 1,184.00	+
10	RADIATOR GRILLE <i>lt</i>	1	\$ 2,367.00	✓
11	RADIATOR GRILLE COVER <i>new</i>	1	\$ 50.00	+
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>lt</i>	1	\$ 722.00	✓
13	FRONT BUMPER CHANNEL COVER - RH <i>new</i>	1	\$ 65.00	+
14	FRONT NUMBER PLATE <i>lt</i>	S/N	\$ 60.00	✓
15	SUNDRIES <i>?</i>		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 10,421.00	
TOTAL LABOUR CHARGES		:	\$ 4,372.00	
GRAND TOTAL		:	\$ 14,793.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adnan
18/12/24

not Authorised, 03 Pags

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT