

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at Work / Site / Home / Other

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vek: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC5466L Yr Regn: 1Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 C/S: _____Colour: White A/C: Insured / Std / Nil / NASp. Reading: 157118 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55 R17R: 225/55 R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/12/24Survey held at PremiumDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

09.11.24

COE Expiry: _____

Estimate given during: Yes (✓)
1st Survey: No ()

MV:

PV:

Nett:

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Addl Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)

Photos

Others

Report Format: _____

Reported by: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0930/2024/EQ
DATE : 17-Dec-24
WIP : 42037

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR THAM WAI LEONG
ADDRESS : 317 TELOK KURAU ROAD
SINGAPORE 423865

TELEPHONE : HP +65 98318781
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800079954-06
VEHICLE NO : **SMC 5466 L**
MODEL CODE : AUDI A6 1.8 TFSI S TRONIC
MODEL YEAR : 7/7/2018
ENGINE NO : CYG 023417
CHASSIS NO : WAUZZZ4GXJN039737
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Dec-24
PLACE OF ACCIDENT : 53 SIMS PL, BLOCK 53, SINGAPORE 380053
BLOCK 53 SIMS PLACE CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 5466 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500
3	TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER.	\$ 2,000.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	✓
TOTAL LABOUR CHARGES		: \$ 4,372.00	


55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 5466 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 3,903.00	+
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 608.00	+
3	FRONT BUMPER FIXING PARTS	1	\$ 61.00	+
4	FRONT BUMPER SECURING STRIP - LH / RH <i>3 new</i>	2	\$ 117.00	+
5	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 160.00	+
6	FRONT BUMPER ADAPTER - RH <i>3 new</i>	1	\$ 48.00	+
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 266.00	+
8	FRONT BUMPER SPOILER - LOWER <i>Repair New</i>	1	\$ 310.00	+
9	FRONT SPOILER <i>Repair</i>	1	\$ 1,184.00	+
10	RADIATOR GRILLE <i>At</i>	1	\$ 2,367.00	✓
11	RADIATOR GRILLE COVER <i>new</i>	1	\$ 50.00	+
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>At</i>	1	\$ 722.00	✓
13	FRONT BUMPER CHANNEL COVER - RH <i>new</i>	1	\$ 65.00	+
14	FRONT NUMBER PLATE <i>At</i>	S/N	\$ 60.00	✓
15	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 10,421.00	
TOTAL LABOUR CHARGES		:	\$ 4,372.00	
GRAND TOTAL		:	\$ 14,793.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *18/12/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 03849*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT