



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: LIM SERENE

Ref: CS/INC24120233/Avh3e2(N)

Date: 25/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNH 4300A	Veh. Inspected	SLA 8418D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1308010-002	Excess (\$)	0.00
Assign From	LIM SERENE	Assign Date	17/12/2024

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHD841CMHU102549	Colour	WHITE
Odometer	129801 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	FALKEN	6 mm
L/H Front Tyre	225/45 R17	FALKEN	6 mm
R/H Rear Tyre	225/45 R17	FALKEN	6 mm
L/H Rear Tyre	225/45 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2024	Inspect Date / Time	17/12/2024 (02:55 PM)
Survey held at	N-51 AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**