

Vehicle: GBF8384J

Make & Model: NISSAN CABSTAR
Chassis No: JN1SC2F24Z0859272

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Tailgate / <i>DD</i>			1459.60 N	
2	Rear Tailgate "70km/h" Sticker / <i>MC</i>			10.00 SN	
3	Rear Tailgate "13 pax" Sticker / <i>MC</i>			10.00 SN	
4	Rear Tailgate Company Sticker / <i>MC</i>			150.00 SN	
5	Rear Tailgate Inner Aluminium Plate / <i>BT</i>			250.00 SN	
6	Right Taillamp / <i>BR</i>			289.30 N	
7	Right Sidegate <i>X R</i>			1869.40 N	
8	Right Sidegate Company Sticker / <i>MC</i>			200.00 SN	
9	Right Sidegate Rear Lock Device / <i>BT</i>			285.90 N	
10	Right Rear End Guide Rubber (<i>Rh</i>) / <i>Tn</i>	<i>21</i>	30.80 N	61.60 N	<i>30.80 /</i>
11					
	Labour				
1	Check Wiring			\$ 50.00	<i>30</i>
2	Panel Beating			\$ 500.00	<i>400</i>
3	Paint Work			\$ 700.00	<i>500</i>

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Stew (LKK)**17/12/24, 3:30 PM**W R**L/S**W A S
4 dy*