

ESTIMATE

13/12/2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Vehicle No: GBG8823D
Vehicle Model: N/NV350
Est No: CBMQ24120146
Claims ref:
Accident Date: 27/11/24
In Charge: JUNIOR
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
----	-------------	-----	----------	-------------

NET ITEMS:

1	TAILGATE	1	PC \$ 2,050.00	\$ 2,050.00 <i>bt</i>
2	TAILGATE LOCK ASSY	1	PC \$ 320.00	\$ 320.00 <i>Xnn</i>
3	TAILGATE EMBLEM "NISSAN" LOGO	1	PC \$ 110.00	\$ 110.00 <i>ner</i>
4	TAILGATE EMBLEM "NV350"	1	PC \$ 100.00	\$ 100.00 <i>ner</i>
5	TAILGATE EMBLEM "URVAN"	1	PC \$ 100.00	\$ 100.00 <i>ner</i>
6	REAR BUMPER	1	PC \$ 750.00	\$ 750.00 <i>de</i>
7	REAR BUMPER CLIPS	10	PC \$ 5.50	\$ 55.00 <i>ner</i>
8	REAR BUMPER LOWER BRACKET RH & LH	2	PC \$ 20.00	\$ 40.00 <i>Xnn</i>
9	REAR BUMPER REINFORCEMENT	1	PC \$ 200.00	\$ 200.00 <i>bt</i>
10	REAR KEYLESS ANTHENA	1	PC \$ 120.00	\$ 120.00 <i>Xnn</i>
11	REAR END PANEL - <i>plumb</i>	1	PC \$ 180.00	\$ 180.00 <i>bt</i>
12	REAR END PANEL TOP GARNISH	1	PC \$ 80.00	\$ 80.00 <i>X</i>
13	REAR FLOOR PANEL - REPAIR	1	PC	\$ -

NET TOTAL S\$

10% DISCOUNT S\$

3545
10% 3190.50
\$ 4,105.00
\$ (410.50)
\$ 3,694.50

SPECIAL NET ITEMS:

1	TAILGATE STICKER "70KM/H"	1	PC \$ 20.00	\$ 20.00 <i>ner</i>
2	TAILGATE STICKER "8PAX"	1	PC \$ 20.00	\$ 20.00 <i>ner</i>
3	TAILGATE STICKER "COMPANY NUMBER"	1	PC \$ 100.00	\$ 100.00 <i>ner</i>
4	REVERSE SENSOR	1	SET \$ 280.00	\$ 280.00 <i>200nw</i>
5	REAR WINDSCREEN SEALANT	1	PC \$ 60.00	\$ 60.00 <i>ner</i>

SPECIAL NET TOTAL S\$

\$ 480.00 *400*

LABOUR CHARGE:

1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS			\$ 800.00 <i>600</i>
2	TO PUTTY SPRAY PAINT ON TAILGATE, REAR END PANEL, REAR BUMPER, REAR FLOOR PANEL			\$ 1,000.00 <i>700</i>

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

13/12/2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Vehicle No: GBG8823D
Vehicle Model: N/NV350
Est No: CBMQ24120146
Claims ref:
Accident Date: 27/11/24
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
3	TO RUST PROOF ON REAR END PANEL, REAR FLOOR PANEL			\$ 100.00 40
4	TO APPLY SPRAY TEROSTAT ON REAR END PANEL, REAR FLOOR PANEL .			\$ 100.00 60
5	TO REMOVE & REFIT TAILGATE MECHANISM & OTHER ATTACHMENT PARTS			\$ 100.00 60
6	TO REMOVE & REFIT REAR WINDSCREEN GLASS			\$ 150.00 120
7	TO CHECK ELECTRICAL & WIRING SYSTEM FOR PROPER FUNCTION			\$ 100.00 K m
TOTAL LABOUR COST S\$				\$ 2,350.00

1580

AMOUNT S\$ \$ 6,524.50
GST @ 9% \$ 587.21
AMOUNT DUE S\$ \$ 7,111.71

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

Taufik 97495749
WP' 23/12/24 5pm
L/S Resurvey after repair
5 days
Taufik C (kkanuto.com)
5170.50
L/S \$4100
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: