

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBU 9218X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR SIDE COVER RED	CUT	200.00	200.00
1	PILLION SIDE COVERSET SILVER LEFT	BROKEN	150.00	150.00
1	PILLION BOTTOM SIDE COVERSET SILVER	BROKEN	180.00	180.00
1	LEFT SIDE FOOTREST COVER BLACK	CUT	220.00	220.00
1	FRONT BOTTOM COVERSET BLACK	BROKEN	200.00	200.00
1	FRONT MIDDLE COVER SET BLACK	BROKEN	180.00	180.00
1	MAIN STAND	BENT	120.00	120.00
1	SIDE STAND	BENT	85.00	85.00
1	LEFT MIDDLE INNERCOVER	CRACKED	180.00	180.00
1	FRONT LEFT SIDE COVERSET RED	BROKEN	250.00	250.00
1	LEFT SIDE SIGNAL FRONT	BROKEN	150.00	115.00
1	LEFT SIDE SIGNAL REAR	CUT	150.00	115.00
1	HANDLE BAR	BENT	220.00	200.00
1	SET LEVER	CUT	150.00	150.00
1	BAR LEVERGUARD	CUT	120.00	120.00
1	LEFT SIDE MIRROR	CUT	220.00	140.00
1	LEFT SIDE PILLION BAR	CUT	160.00	160.00
1	CVT CASING SILVER	CUT	280.00	260.00
1	CVT COVER BLACK	CUT	120.00	120.00
1	FORKSET	NOT NECESSARY	800.00	-
1	FOOTREST RUBBER	CUT	95.00	95.00
1	WINGS CASING	MISSING	85.00	60.00
1	LOGO	SCRATCHED	45.00	45.00
1	TAIL LIGHT MUDGUARD	CRACKED	85.00	85.00
	LESS 10% DISCOUNT		-444.50	-343.00
			4,000.50	3,087.00
	<u>LABOUR</u>			
	PRESS BODY.		450.00	200.00

Report Ref No. CS/FCI24120249/Evp3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,850.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR.		800.00	300.00
			1,250.00	500.00
	GRAND TOTAL		5,250.50	3,587.00

Report Ref No. CS/FCI24120249/Evp3m4(N)

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.