



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERS SINGAPORE 048623 ATTN: HWANG SHIANG YI			Ref: CS/SMO24120250/Knp3e2(N) Date: 21/01/2025 Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKZ 8123J
	Policy No.	D23MTPV01014216	Coverage (\$)	0.00
	Claim No.	CMTD2404039/SYH	Excess (\$)	0.00
	Assign From	HWANG SHIANG YI	Assign Date	18/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALPHARD (A)	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	AGH300032567	Colour	METALLIC BLACK
	Odometer	194516 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/40Z R19	DUNLOP	4 mm
	L/H Front Tyre	255/40Z R19	DUNLOP	4 mm
	R/H Rear Tyre	255/40Z R19	DUNLOP	4 mm
	L/H Rear Tyre	255/40Z R19	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION.			
5. General Information				
	Accident Date	14/12/2024	Inspection Date	18/12/2024
	Survey held at	1 YISHUN INDUSTRIAL STREET 1 #01-06 A'POSH BIZHUB		
	Repairer	ELITE AM PTE. LTD.		
5a. Remarks				
	A) THE MARKET VALUE IS S\$56,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days