



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: MOHD SHARIN			Ref: CS/LIP24120261/Kqh3e2(N) Date: 16/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNF 6963M	Veh. Inspected	SLG 8577X
	Policy No.		Coverage (\$)	0.00
	Claim No.	DVS24/0306	Excess (\$)	0.00
	Assign From	MOHD SHARIN	Assign Date	18/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JTDKB3FU803536160	Colour	METALLIC PEARL WHITE
	Odometer	327227 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	ROADBOSS	9 mm
	L/H Front Tyre	195/65 R15	ROADBOSS	9 mm
	R/H Rear Tyre	195/65 R15	ROADBOSS	9 mm
	L/H Rear Tyre	195/65 R15	ROADBOSS	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/12/2024	Inspection Date	19/12/2024
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)REGISTRATION DATE: 17 OCT 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	