



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 7564X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR RH FENDER	TO REPAIR SEE LABOUR	2,072.50	-
1	REAR RH TAILLAMP	CUT	1,022.70	815.00
1	REAR RH TAILLAMP LOWER GARNISH	TO REPAIR SEE LABOUR	496.00	-
	LESS 25% DISCOUNT		-897.80	-203.75
			2,693.40	611.25
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR RH DOOR 'AUTO DOOR' STICKER (SN)	NOT NECESSARY	150.00	-
1	REAR RH DOOR 'PRESS TO OPEN' STICKER (SN)	NOT NECESSARY	120.00	-
			270.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		80.00	30.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR).	NOT NECESSARY	80.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACIDENT. INCLUSIVE OF THE REPAIR OF REAR RH FENDER AND REAR RH TAILLAMP LOWER GARNISH.		1,000.00	100.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			2,280.00	630.00
	<b>GRAND TOTAL</b>		<b>5,243.40</b>	<b>1,241.25</b>

Report Ref No. CS/INC24120266/Aqh3m4(N)



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,000.00</b>
---	--	--	-----------------

Report Ref No. CS/INC24120266/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 2,963.40 \$ 611.25

TOTAL FOR LABOUR : \$ 2,280.00 \$ 630.00

TOTAL REPAIR COST: \$ 5,243.40 \$ 1,241.25

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.