



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: AZHARI AFIDI

Ref: CS/INC24120266/Aqh3m4(N)

Date: 24/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 9805E	Veh. Inspected	SMM 7564X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305608-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	18/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800374844	Colour	BLACK
Odometer	363701 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	NEXEN	6 mm
L/H Front Tyre	195/65R15	NEXEN	6 mm
R/H Rear Tyre	195/65R15	NEXEN	6 mm
L/H Rear Tyre	195/65R15	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/11/2024	Inspect Date / Time	18/12/2024 (12:12 PM)
Survey held at	N-51 AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**