

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

17/12/2024

SMRT BUSES LTD

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Vehicle No: SMU8202S

Vehicle Model: HONDA FIT

Est No: CBMQ24120164

Claims ref:

Accident Date: 12/12/24

In Charge: JUNIOR

Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	REAR BUMPER	1	PC \$ 680.00	\$ 680.00
2	REAR BUMPER RETAINER RH	1	PC \$ 35.00	\$ 35.00
3	REAR BUMPER CLIPS	10	PC \$ 4.00	\$ 40.00
4	REAR FENDER RH - REPAIR	1	PC	\$ -
5	REAR FENDER INNER SHIELD CLIPS	10	PC \$ 4.00	\$ 40.00
6	REAR FENDER INNER SHIELD RH	1	PC \$ 380.00	\$ 380.00
LIST TOTAL S\$				\$ 1,175.00
20% DISCOUNT S\$				\$ (235.00)
				<u>\$ 940.00</u>
LABOUR CHARGE:				
1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS			\$ 600.00
2	TO PUTTY SPRAY PAINT ON REAR FENDER RH, REAR BUMPER			\$ 600.00
3	TO REMOVE & REFIT REAR FENDER INNER TRIM RH & OTHER ATTACHMENT PARTS			\$ 100.00
TOTAL LABOUR COST S\$				<u>\$ 1,300.00</u>



AMOUNT S\$ \$ 2,240.00
GST @ 9% \$ 201.60
AMOUNT DUE S\$ \$ 2,441.60

Customer's Signature

MOVA AUTOMOTIVE PTE LTD