

Name &amp; Address:

**Motor Claims Department**  
**CHINA TAIPING INSURANCE P/L**  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

Vehicle No:

**SMM7436H**

Date:

20-May-25

Brand &amp; Model:

BMW 116i M Sport

Franchise:

BMW

Email/Fax No:

Contact No:

Chassis/VIN No:

**WBA7K120007P23315**

Contact Person (Eurokars):

FAIZ

Type of Claim:

THIRD PARTY

YEAR MODEL:

30/04/2024

WIP#:

**31581**

Contact No (Eurokars):

6331 0680

**PARTS / MATERIAL CHARGES**

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER	51 12 9881580	1		\$ 1,132.45	\$ 1,132.45
2	LOWER TRIM PANEL	51 12 8070950	1		\$ 269.65	\$ 269.65
3	CLAMP	07 14 7332700	6		\$ 20.10	\$ 20.10
4	EXPANDING RIVET	07 14 7148444	8		\$ 22.00	\$ 22.00
5	TOWING COVER	51 12 9881582	1		\$ -	\$ 56.50
6	COVER, BUMPER LH	51 12 8075311	1		\$ -	\$ 78.10
7	COVER, BUMPER RH	51 12 8075312	1		\$ -	\$ 78.10
8	HOLDER, WHEELARCH RH	51 12 8075314	1		\$ -	\$ 50.55
9	HOLDER WHEELARCH LH	51 12 8075313	1		\$ -	\$ 50.55
10	CORNER BUMPER MOUNT LH	51 12 7461397	1		\$ -	\$ 53.70
11	CORNER BUMPER MOUNT RH	51 12 7461398	1		\$ -	\$ 53.70
12	ABSORBER FUNNEL LH	51 12 8095409	1		\$ -	\$ 55.50
13	ABSORBER FUNNEL RH	51 12 8095410	1		\$ -	\$ 52.05
14	SIDE BUMPER MOUNT LH	51 12 8072575	1		\$ -	\$ 143.85
15	SIDE BUMPER MOUNT RH	51 12 8072576	1		\$ -	\$ 143.85
16	GUIDE, CENTER	51 12 8496655	1		\$ -	\$ 172.60
17	MOUNT FOR SMART OPENER	51 12 8072572	2		\$ 247.70	\$ 247.70
18	PLUG-IN NUT	51 12 7461407	6		\$ 19.20	\$ 19.20
19	REAR REINFORCEMENT	51 12 7462338	1		\$ -	\$ 477.95
20	WASHER-GASKET	51 12 7300789	2		\$ -	\$ 23.80
21	REFLECTOR, LH	63 14 8077173	1		\$ -	\$ 43.50
22	REFLECTOR, RH	63 14 8077174	1		\$ -	\$ 43.50
23	REVERSE SENSOR	66 20 9826784	2		\$ -	\$ 539.30
24	SENSOR SEAL	66 20 9390408	4		\$ 22.60	\$ 22.60
25	BMW LOGO	51 14 8492586	1		\$ 76.55	\$ 76.55
26	REAR MUFFLER	18 30 8694336	1		\$ -	\$ 1,176.05
27	CLAMPING BUS	18 30 7560779	1		\$ -	\$ 68.95
28	EXHAUST PIPE TIP	18 30 8668527	1		\$ -	\$ 129.30
29	RP GASOLINE	18 30 9845197	1		\$ -	\$ 4,563.60
30	SCREW CLAMP	18 30 5A04BD5	1		\$ -	\$ 47.55

	SUPPLEMENTARY					
31	TAILGATE	41 00 9627390	1		\$ 1,374.60	\$ 1,374.60
32	BLIND RIVET	32 41 1094185	6		\$ 27.30	\$ 27.30
33	EXPANDING NUT	07 14 7429950	2		\$ 6.10	\$ 6.10

Sub-Total (Parts Price) \$ 3,218.25 \$ 11,320.80

LABOUR / SERVICES CHARGES			
NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER, REAR REINFORCEMENT AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 850.00	\$ 2,125.00
2	TO RESPRAY REAR BUMPER AND TAILGATE.	\$ 1,880.00	\$ 2,320.00
3	TO SUPPLY REAR LICENCE PLATE WITH CASING.	\$ -	\$ 70.00
4	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	\$ -	\$ 1,700.00
5	TO TRANSFER THE REVERSE SENSORS.	\$ 250.00	\$ 500.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 350.00	\$ 500.00
8	SUNDRIES.	\$ 20.00	\$ 50.00
	SUPPLEMENTARY		
9	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS.	\$ 560.00	\$ 560.00
10	TO SUPPLY SEALANT FOR REAR WINDSCREEN GLASS.	\$ 119.00	\$ 119.00
11	TO SUPPLY REAR LICENSE PLATE WITH CASING.	\$ 150.00	\$ 150.00

Survey Date & Time:	Repair Days:6 Days	Excess:
---------------------	--------------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ 4,329.00 \$ 8,344.00

	REVISED	PRICE
Parts Price	\$ 3,218.25	\$ 11,320.80
Labour Price	\$ 4,329.00	\$ 8,344.00
Total (Initial Estimate)	\$ 7,547.25	\$ 19,664.80
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ 7,547.25	\$ 19,664.80
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ 7,547.25	\$ 19,664.80
GST 9%	\$ 679.25	\$ 1,769.83

GRAND TOTAL

\$	8,226.50	\$	21,434.63
----	----------	----	-----------