



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN LEE

Ref: CS/INC24120283/Avh3m4(N)

Date: 28/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 9524G	Veh. Inspected	SNL 3050G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1308914-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	18/12/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	GB73150771	Colour	BLACK
Odometer	82177 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65R15	CEAT	6 mm
L/H Front Tyre	185/65R15	CEAT	6 mm
R/H Rear Tyre	185/65R15	CEAT	6 mm
L/H Rear Tyre	185/65R15	CEAT	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/12/2024	Inspect Date / Time	19/12/2024 (01:48 PM)
Survey held at	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**