



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: SERENE		Ref: CS/FCI24120304/Knp3m4(N) Date: 24/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8380H	Veh. Inspected	SLX 1982R
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24011050MFCT	Excess (\$)	0.00
Assign From	SWEE KEONG TEO	Assign Date	19/12/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALPHARD (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTNGF3DH708008818	Colour	METALLIC BLACK
Odometer	116525 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50R18	BRIDGESTONE	6 mm
L/H Front Tyre	235/50R18	BRIDGESTONE	6 mm
R/H Rear Tyre	235/50R18	BRIDGESTONE	6 mm
L/H Rear Tyre	235/50R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/12/2024	Inspection Date	24/12/2024
Survey held at	CH CHUAN HO PTE LTD 160 SIN MING DRIVE #07-09, SIN MING AUTOCITY, SINGAPORE 575722		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	