

# ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	09:33 HRS	BUS REGISTRATION NUMBER	SG6031J
ACCIDENT DATE	17-Dec-24	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	PUVANESWARAN A/L SELUARASSI	BUS ROUTE NO.	
THIRD PARTY CLAIM AGAINST	India International Insurance	BUS ADVERT (Y/N)	N

## SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	NS FRONT VIEW MIRROR ASSY / BT/CV	1	\$ 1,584.00
2	REFLECTIVE STICKER / M	2	\$ 11.00
	1595.00	9% GST	\$ 143.55
	-10%		
	1435.50	PARTS TOTAL COST	\$ 1,738.55

## SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • DISMANTLE AND REPLACE ITEM NO :1-2	325 / \$ 1,300.00
SPRAY PAINTING \$640 PER PANEL	9% GST \$ 117.00
LABOUR CHARGES \$650 PER DAY	325
	LABOUR TOTAL COST \$ 1,417.00

## SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

P/P = \$1760.50

BUS TYPE (SD / DD)	DD	DATE IN	17/Dec/2024
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	1
		LOSS OF USE COST	\$400.00

Stew (LKK)  
20/12/24, 10:30 AM  
w  
P/P  
y Bel  
1 day

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SUMMARY	
SECTION NO.	COST
1	\$ 1,738.55
2	\$ 1,417.00
3	\$ 400.00
TOTAL	\$ 3,555.55