

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 93911482

TO	:	DATE	: 20-Dec-24
ATTENTION	:	JOB TYPE	: T/P CLAIM
	:	VEHICLE DETAILS	
	:	VEHICLE NO	: SNC3155K
	:	MODEL	: TOYOTA ALTIS

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER X (not mounted) nn	1	\$ 821.00	\$ 821.00
2	BONNET X (not mounted) nn	1	\$ 950.00	\$ 850.00
3	SIDE MIRROR LH X R	1	\$ 612.00	\$ 612.00
4	FRONT FENDER LH - nn	1	\$ 798.00	\$ 798.00
5	FRONT FENDER EMBLEM 'HYBRID' LH - nnc	1	\$ 52.00	\$ 52.00
6	FRONT FENDER COWLING X nn	1	\$ 212.00	\$ 212.00
7	FRONT DOOR LH - nn	1	\$ 1,258.00	\$ 1,258.00
8	HEADLAMP LH X (not mounted) nn	1	\$ 3,598.00	\$ 3,598.00

TOTAL PRICE	\$ 8,201.00
LESS 25%	\$ 2,050.25
SUB TOTAL PRICE	\$ 6,150.75

658 /

/

1150 /

1,860

-25%

1,395

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS X nn	10	\$ 6.50	\$ 65.00
2	FRONT FENDER COWLING CLIP X nn	8	\$ 6.50	\$ 52.00
3	FRONT SPORTS RIM X (not mounted) nn	1	\$ 1,200.00	\$ 1,200.00

TOTAL \$ 1,317.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$800.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$800.00	450	

5	WIRING CHECK	\$200.00	30	
6	RESET ENGINE TROUBLE CODE	\$300.00	X	
7	REFOCUS HEADLAMP BEAM	\$60.00	X	

880

TOTAL \$2,160.00

TOTAL PARTS COST : \$ 7,467.75
TOTAL LABOUR COST : \$ 2,160.00
TOTAL REPAIR COST : \$ 9,627.75

2,275

L/S - 1,820
= 1800

Steve (LKK)
20/12/24, 11.30am
in IL
L/S
4 M L
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: