

**ELITE AUTO RESTORATION PTE LTD**

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 202424577D

Vehicle Number : SNM1684K  
Vehicle Model : TOYOTA VOXY  
Accident Date : 11.12.2024  
Original Reg Date : 30.08.2023

Date : 26.11.2024  
Chassis : ZWR900090364  
TP Ins. INCOME

**ESTIMATE**

|          |      |                                     |       |          |   |
|----------|------|-------------------------------------|-------|----------|---|
| 1        | 1 pc | SIDE SLIDING DOOR RH                |       | 2,183.00 | + |
| 2        | 1 pc | SLIDING DOOR WEATHERSTRIP RH(DOOR)  |       | 189.60   | + |
| 3        | 1 pc | SLIDING DOOR STOPPER                | 35.00 | 70.00    | + |
| 4        | 1 pc | SLIDING DOOR INNERLOCK              |       | 298.60   | + |
| 5        | 1 pc | SLIDING DOOR CATCH                  |       | 38.60    | + |
| 6        | 1 pc | SIDE DOOR OUTER GARNISH             | NP    | 398.50   | + |
| 7        | 1 pc | SIDESKIRT LH                        | NP    | 725.90   | + |
| 8        | 1 pc | REAR FENDER LH                      |       | 1,895.60 | + |
| 9        | 1 pc | REAR FENDER OUTER GARNISH LH        |       | 125.70   | + |
| 10       | 1 pc | REAR FENDER INNERTRIM RH            |       | 1,023.50 | + |
| 11       | 1 pc | REAR FENDER INNER COWLING RH(FRONT) |       | 186.20   | + |
| 12       | 1 pc | REAR FENDER INNER COWLING RH (REAR) |       | 178.60   | + |
| 13       | 1 pc | REAR BUMPER                         |       | 705.20   | + |
| 14       | 1 pc | REAR BUMPER RETAINER LH             |       | 98.60    | + |
| 15       | 1 pc | REAR BUMPER REFLECTOR WITH COVER LH |       | 235.80   | + |
| 16       | 1 pc | REAR CORNER BUMPER LH               |       | 285.90   | + |
| 17       | 1 pc | REAR RIM LH                         |       | 1,236.50 | + |
| 18       | 1 pc | REAR WHEEL HUB BEARING              |       | 1,169.80 | + |
| 19       | 1 pc | REAR ABSORBER RH                    |       | 345.80   | + |
| subtotal |      |                                     |       | 8,117.60 |   |
| Less 25% |      |                                     |       | 1,623.52 |   |
| total    |      |                                     |       | 6,494.08 |   |

**Special Nett**

|          |       |                                 |  |        |   |
|----------|-------|---------------------------------|--|--------|---|
| 1        | 1 set | Rear door inner trim clips      |  | 30.00  | + |
| 2        | 1 set | Rear Bumper clips               |  | 30.00  | + |
| 3        | 1 set | Sideskirt clips                 |  | 30.00  | + |
| 4        | 1 set | Rear fender inner cowling clips |  | 30.00  | + |
| 5        | 1 pc  | Rear sport rim tyre             |  | 450.00 | + |
| subtotal |       |                                 |  | 570.00 |   |

### Labour charge

|                                        |  |                    |     |
|----------------------------------------|--|--------------------|-----|
| Panel Beating                          |  | 1,800.00           | 200 |
| Spray painting                         |  | 1,800.00           | 200 |
| Anti rust                              |  | 120.00             | +   |
| Perform computerised wheel alignment   |  | 120.00             | 80  |
| Remove and install rear undercarriage  |  | 30.00              | P ✓ |
| Remove and install side door mechanism |  | 200.00             | +   |
|                                        |  | <u>\$ 4,070.00</u> |     |

510

total

11,134.08

Adrian Lj  
L/s 26/12/24  
03 Days

total 1945.15  
L/s 1.5K ✓

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: